

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instructions
verse side)

CATE
OR 10

Budget approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME <i>MCA Unit</i>
2. NAME OF OPERATOR <i>Conoco Inc.</i>	8. FARM OR LEASE NAME <i>MCA Unit Bldg 2-</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>	9. WELL NO. <i>318</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>25' FNA & 1295' FEA - Unit Letter A</i>	10. FIELD AND POOL, OR WILDCAT <i>Maljamar G-SA</i>
14. PERMIT NO. <i>30-025-24196</i>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>28-17S-32E</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <i>Lea</i>
	13. STATE <i>NM</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started on 4/11/88. MIRR. Run csq scraper. G-11H w/ mudshoe & string mill. Mill tight spot from 3816' - 20'. Set pke at 4038' & test RBP. Test Hg & csq to 2000 psi. Release pke. Tag & WO bridge plug at 4083'. Wash to 4135'. POOH & recovered part of BP. Set pke at 4038'. Pumped 15 bbls 15% HCL acid. Pull up & reset pke at 3850' to check communication between 6th & 7th zone, no communication. Release pke. Pump 7th zone w/ 11 spf from 3918' - 4011'. Acidize 7th zone w/ 36 bbls 15% HCL-NE-FE acid. Repeat 7th zone & 6th zone from 3766' to 3878'. Pumped 15 bbls of 15% acid. Run producing equipment & place on production. Work Completed on 4/26/88.

18. I hereby certify that the foregoing is true and correct

SUB *[Signature]* *IF FINNEY*

TITLE *Administrative Supervisor*

DATE *June 27, 1988*

19. Space for General or State office use

20. SIGNATURES OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

535

It is a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.
BAM - Campbell - (16) OXU (1) FPA (1) ZP.