

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. State Oil & Gas Lease No.
2. Name of Operator GREAT WESTERN DRILLING COMPANY		7. Unit Agreement Name
3. Address of Operator P. O. BOX 1659 MIDLAND TEXAS 79701		8. Farm or Lease Name E. L. HARROD
4. Location of Well UNIT LETTER I 1980 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE EAST LINE, SECTION 7 TOWNSHIP 16-S RANGE 35-E NMPM.		9. Well No. 1
15. Elevation (Show whether DF, RT, GR, etc.) 4039.9 GR		10. Field and Pool, or Wildcat EIDSON-PENN
12. County LEA		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.			

Rigged up casing pullers 6-23-73, filled hole with mud and spotted first plug (25 sx) at 10,746'. Shot and pulled 4 1/2" casing at 10,010'. Set additional plugs as follows:

60 sx at 10,000'
35 sx at 8250'
50 sx at 7625'
60 sx at 6690'
35 sx at 6300'
35 sx at 4660'

Shot and pulled 318' of 8 5/8" casing. Set 130 sx plug at 382' and a 10 sx plug and a permanent marker at the surface July 2, 1973. Notice will be given when final cleanup has been made and location is ready for inspection.

3. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <i>R. I. Comstock</i>	R. I. Comstock	TITLE Chief Engineer	DATE 7-31-73
APPROVED BY <i>John W. Rung</i>		TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:			