	UNITED STATES	FORM APPROVED
(June 1990) N.M. OH COMPARING	LANDWANAGEMENT	Budget Bureau No. 1004-0135 Expires: March 31, 1993
P.O. Box 1980		5. Lease Designation and Senal No.
Hobbe NM 89241	S AND REPORTS ON WELLS	LC 057210
SUNDRYNDICE	S AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or to dee Use "APPLICATION FOR PERMIT " for	pen or reentry to a different reservoir.	
		7. If Unit or CA, Agreement Designation
1. Type of Well	N TRIPLICATE	
X Oil Gas INJECTION Well Well Other		
2. Name of Operator		8. V
CONOCO, INC. 3. Address and Telephone No.		MCA Unit
10 Desta Dr., Suite 100W, Midland, Texas 79705-4500,915 686-5424 915 684-6381 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 915 684-6381		Well # 348/30 025 2452 10. Field and Pool, or Exploratory Area Maljamar Grayburg San Andre 11. County or Parish State
Surface: I345' FSL & 25' FEL		Maljamar Grayburg San Andre
TD: Sec 27, TI7S, R32E		11. County or Parish, State
		Lea, NM
12 CHECK APPROPRIATE BOX(s) TO IND TYPE OF SUBMISSION	ICATE NATURE OF NOTICE, REPORT, (DR OTHER DATA
	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
X Subsequent D	Recompletion	New Construction
X Subsequent Report	Pługging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
	Clean out & run new string tbg	Dispose Water
	Add perfs & acidize	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
 Describe Proposed or Completed Operations (Clearly state all periodirectionally drilled, give subsurface locations and measured at the unseat pump, Remove WH, ins 12-4-97: POOH w/rods, tagged fill @ 4210', 12-5-97: RIH w/new 2 3/8" tbg, tagged fill @ 12-8-97: Rigged up wireline, RIH & perf w/2 12-9-97: Rigged up BJ, spot 15% acid across 12-10-97: RIH with new 2 3/8" tubing, SN @ running rods & pump. SION. 12-II-97: Spaced out well, loaded tbg, tested 	Add perfs & acidize inent details, and give pertinent dates, including estimated date ind true vertical depths for all markers and zones pertinent to this ing tool, RIH w/paraffin cutter, cut to top of tall BOP, SION. inspect tubing out of hole, SION. 2 42II', cleaned out to 4300', POOH. SION 2 JSPF @ 4073'-4145', ran in hole to 419I', S ss perfs, rigged up swab, swabbed, rigged 2 4215', bottom of tbg @ 4225', removed B0	Phote: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)*
 I2-3-97: Rig up, POOH w/rods, RIH w/fish to unseat pump, Remove WH, ins I2-4-97: POOH w/rods, tagged fill @ 4210', I2-5-97: RiH w/new 2 3/8" tbg, tagged fill @ 12-8-97: Rigged up wireline, RIH & perf w/2 I2-9-97: Rigged up BJ, spot I5% acid across I2-10-97: RIH with new 2 3/8" tubing, SN @ running rods & pump. SION. I2-II-97: Spaced out well, loaded tbg, tested 	Add perfs & acidize inent details, and give pertinent dates, including estimated date ind true vertical depths for all markers and zones pertinent to this ing tool, RIH w/paraffin cutter, cut to top of tall BOP, SION. ; inspect tubing out of hole, SION. @ 42II', cleaned out to 4300', POOH. SION 2 JSPF @ 4073'-4I45', ran in hole to 4I9I', S ss perfs, rigged up swab, swabbed, rigged @ 42I5', bottom of tbg @ 4225', removed Bo I pump - well put on production.	Phote: Report results of multiple completion on Well Completion or Recompletion Report and Lag form.) of starting any proposed work. If well is :work.)* fish, unable to SION. downer DOOLL_OLONE
 I2-3-97: Rig up, POOH w/rods, RIH w/fish to unseat pump, Remove WH, ins I2-4-97: POOH w/rods, tagged fill @ 4210', I2-5-97: RIH w/new 2 3/8" tbg, tagged fill @ 12-8-97: Rigged up wireline, RIH & perf w/2 I2-9-97: Rigged up BJ, spot I5% acid across I2-10-97: RIH with new 2 3/8" tubing, SN @ running rods & pump. SION. 	Add perfs & acidize inent details, and give pertinent dates, including estimated date and true vertical depths for all markers and zones pertinent to this ing tool, RIH w/paraffin cutter, cut to top of tall BOP, SION. 9 42II', cleaned out of hole, SION. 9 42II', cleaned out to 4300', POOH. SION 2 JSPF @ 4073'-4I45', ran in hole to 4I9I', S ss perfs, rigged up swab, swabbed, rigged 9 42I5', bottom of tbg @ 4225', removed Bo 1 pump - well put on production. ACCEPTE CLICAL COLL MAR	Proce: Report results of multiple completion on Well Completion or Recompletion Report and Lag form.) of starting any proposed work. If well is work.)* fish, unable to SION. down, POOH, SION. DP, installed WH, DFOR RECORD DAVID B. CLASS 0 6 1998
 I2-3-97: Rig up, POOH w/rods, RIH w/fish to unseat pump, Remove WH, ins I2-4-97: POOH w/rods, tagged fill @ 4210', I2-5-97: RiH w/new 2 3/8" tbg, tagged fill @ 12-8-97: Rigged up wireline, RIH & perf w/2 I2-9-97: Rigged up BJ, spot I5% acid across I2-10-97: RIH with new 2 3/8" tubing, SN @ running rods & pump. SION. I2-II-97: Spaced out well, loaded tbg, tested 	Add perfs & acidize inent details, and give pertinent dates, including estimated date ind true vertical depths for all markers and zones pertinent to this ing tool, RIH w/paraffin cutter, cut to top of tall BOP, SION. ; inspect tubing out of hole, SION. @ 42II', cleaned out to 4300', POOH. SION 2 JSPF @ 4073'-4I45', ran in hole to 4I9I', S ss perfs, rigged up swab, swabbed, rigged @ 42I5', bottom of tbg @ 4225', removed Bo I pump - well put on production.	Proce: Report results of multiple completion on Well Completion or Recompletion Report and Lag form.) of starting any proposed work. If well is work.)* fish, unable to SION. down, POOH, SION. DP, installed WH, DFOR RECORD DAVID B. CLASS 0 6 1998
I2-3-97: Rig up, POOH w/rods, RIH w/fish to unseat pump, Remove WH, ins I2-4-97: POOH w/rods, tagged fill @ 4210', I2-5-97: RIH w/new 2 3/8'' tbg, tagged fill @ I2-8-97: Rigged up wireline, RIH & perf w/2 I2-9-97: Rigged up BJ, spot I5% acid across I2-10-97: RIH with new 2 3/8'' tubing, SN @ running rods & pump. SION. I2-II-97: Spaced out well, loaded tbg, tested	Add perfs & acidize inent details, and give pertinent dates, including estimated date and true vertical depths for all markers and zones pertinent to this ing tool, RIH w/paraffin cutter, cut to top of tall BOP, SION. , inspect tubing out of hole, SION. 2 42II', cleaned out to 4300', POOH. SION 2 JSPF @ 4073'-4I45', ran in hole to 4I9I', S ss perfs, rigged up swab, swabbed, rigged 2 42I5', bottom of tbg @ 4225', removed BO 1 pump - well put on production. ACCEPTE CALCA MAR MAR Ann E. Ritchie	Proce: Report results of multiple completion on Well Completion or Recompletion Report and Lag form.) of starting any proposed work. If well is work.)* fish, unable to SION. down, POOH, SION. DP, installed WH, D FOR RECORD D. DAVID B. CARE 10 6 1998 BLM
I2-3-97: Rig up, POOH w/rods, RIH w/fish to unseat pump, Remove WH, ins I2-4-97: POOH w/rods, tagged fill @ 4210', I2-5-97: RIH w/new 2 3/8" tbg, tagged fill @ I2-8-97: Rigged up BJ, spot I5% acid across I2-10-97: RIH with new 2 3/8" tubing, SN @ running rods & pump. SION. I2-II-97: Spaced out well, loaded tbg, tested I hereby certify that the foregoing is fue and form Signed	Add perfs & acidize inent details, and give pertinent dates, including estimated date ind true vertical depths for all markers and zones pertinent to this ing tool, RIH w/paraffin cutter, cut to top of tall BOP, SION. , inspect tubing out of hole, SION. 2 4211', cleaned out to 4300', POOH. SION 2 JSPF @ 4073'-4145', ran in hole to 4191', S ss perfs, rigged up swab, swabbed, rigged 2 4215', bottom of tbg @ 4225', removed Bo 1 pump - well put on production. ACCEPTE CACCEP	Prote: Report results of multiple completion on Weal Completion or Recompletion Report and Lag form.) of Starting any proposed work. If well is twork.)* fish, unable to SION. down, POOH, SION. DP, installed WH, D FOR RECORD DJ DAVID B BLM Date 2-23-98
I2-3-97: Rig up, POOH w/rods, RIH w/fish to unseat pump, Remove WH, ins I2-4-97: POOH w/rods, tagged fill @ 4210', I2-5-97: RiH w/new 2 3/8" tbg, tagged fill @ I2-8-97: Rigged up BJ, spot I5% acid across I2-10-97: RIH with new 2 3/8" tubing, SN @ running rods & pump. SION. I2-II-97: Spaced out well, loaded tbg, tested I-II-97: Spaced out well, loaded tbg, tested Signed	Add perfs & acidize inent details, and give pertinent dates, including estimated date ind true vertical depths for all markers and zones pertinent to this ing tool, RIH w/paraffin cutter, cut to top of tall BOP, SION. , inspect tubing out of hole, SION. 2 4211', cleaned out to 4300', POOH. SION 2 JSPF @ 4073'-4145', ran in hole to 4191', S ss perfs, rigged up swab, swabbed, rigged 2 4215', bottom of tbg @ 4225', removed Bo 1 pump - well put on production. ACCEPTE CACCEP	Prote: Report results of multiple completion on Weal Completion or Recompletion Report and Lag form.) of Starting any proposed work. If well is twork.)* fish, unable to SION. down, POOH, SION. DP, installed WH, D FOR RECORD DJ DAVID B BLM Date 2-23-98



5

BLM ROGWELL, NM

FEB 27 '98

.

RECEIVED

۰.