

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ <u>Injection</u>	7. UNIT AGREEMENT NAME <u>MCA</u>
2. NAME OF OPERATOR <u>CONOCO INC.</u>	8. FARM OR LEASE NAME <u>MCA Unit Bty 4</u>
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>	9. WELL NO. <u>350</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>Unit L</u>	10. FIELD AND POOL, OR WILDCAT <u>Maljamar 6/5A</u>
14. PERMIT NO. <u>30-025-24546</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 26-17S-32E</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>2615' FSL & 1295' FWL</u>	12. COUNTY OR PARISH <u>Lca</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☒ <u>Repair Communication</u>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① MIRU. Shot 4 holes @ 800'. Set pkr @ 762'. Load & test backside to 500 psi. Pumped 20 bbls Flo-Chck & 2 bbls FW spacer.
- ② POOH w/ pkr. Ran scraper to 1000'. Set pkr @ 830'. Spotted 1 bbl 15% HCl acid across sqz. POOH w/ pkr. Set cmt retainer @ 767'.
- ③ Pumped 225 sxs Thix-o-tropic class "H" cmt w/ 2% CaCl₂. Left 4' cmt on top of retainer.
- ④ DO cmt to 814' and fell out. Shot 1 perf @ 1775'. Set pkr @ 1687'. POOH w/ pkr. Set cmt ret @ 1687'. Pumped 25 bbls Flo-Chck followed by 200 sxs Thix-o-tropic class "H" cmt. WOC.
- ⑤ Drill cmt & retainer from 1685'-1730'. POOH w/ RBP.
- ⑥ Return to injection. Rig down on 12/4/86.

18. I hereby certify that the foregoing is true and correct

SIGNED DE FINNEY

TITLE Administrative Supervisor

DATE 3-6-87

FOR SOURCE OF INFORMATION OR STATE OFFICE USE:

APPROVAL OF
SUPERVISOR OF APPROVAL, IF ANY:

TITLE

DATE

*See instructions on Reverse Side

This document, when used, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CC: Rennie & Put L

BLM-Carlsbad (6) ARCO (2) Cities (1) Petro-Lewis (1) NMOC-Hobbs (3) FI