

Submit 3 Copies To Appropriate District  
Office

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

District I  
1625 N. French Dr., Hobbs, NM 88240

District II  
811 South First, Artesia, NM 88210

District III  
1000 Rio Brazos Rd, Aztec, NM 87410

District IV  
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Well API NO. 30-025-24550
5. Indicate Type or Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: GOODRICH COM.
8. Well No. 1
9. Pool name or Wildcat AUSTIN WOLFCAMP, SOUTHWEST

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well  
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Harvey E. Yates Company

3. Address of Operator  
P.O. Box 1933, Roswell, NM 88202 1-505-623-6601

4. Well Location  
Unit Letter F : 1,980 feet from the NORTH line and 1,980 feet from the WEST line  
Section 11 Township 15S Range 35E NMPM County EDDY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3977' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completion: Attach wellbore diagram of proposed completion or recompilation.

CURRENT PERFS: 10,298-10,304'

SET CIBP @ 10,250' PLUS 30' CMT OR 100' CMT PLUG & TAG  
FREE POINT & CUT 5 1/2" @ APPROX. 8350' & PULL.  
SPOT 100' PLUG ( 50' IN & OUT OF STUB ) & TAG  
SPOT 100' PLUG @ 6147' ( TOP OF GLORIETA ) & TAG  
SPOT 100' PLUG @ 4750' ( INTERM. SHOE PLUG ) & TAG  
SPOT 25 SX PLUG @ 1974' ( TOP OF SALT )  
RELEASE BOWEN CASING PATCH @ 1305' AND PULL 8 5/8"  
SPOT 100' PLUG ( 50' IN & OUT OF STUB ) & TAG  
SPOT 100' PLUG @ 440 TO 340' ( SURFACE SHOE PLUG ) & TAG  
SPOT 50' OR 10 SX PLUG AT SURFACE.  
INSTALL DRYHOLE MARKER.  
BACKFILL WORK PIT. CUT OFF DEADMEN AND CLEAN LOCATION.  
ABOVE APPROVED PER GARY WINK 1-13-2000 (RFN)

CALL OCD I ( HOBBS ) 24 HOURS PRIOR TO START

THE COMPLETION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE START OF  
PLUGGING OPERATIONS AND THE PLAN  
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE 

TITLE PROD. MGR. / ENGINEER Date 1/17/00

TYPE OR PRINT NAME RAY F. NOKES

TELEPHONE NO. 1-505-623-6601

(This space for State use)

APPROVED BY  
Conditions of approval, if any:

TITLE Date