

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Gantt
9. Well No. 1
10. Field and Pool, or Wildcat Undes. Shoebar North
12. County Lea

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Dry
2. Name of Operator Manzano Oil Corporation 915/623-1996
3. Address of Operator P.O. Box 571, Roswell, NM 88202
4. Location of Well UNIT LETTER P 555 FEET FROM THE South LINE AND 765 FEET FROM THE East LINE, SECTION 12 TOWNSHIP 16-S RANGE 35-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3960' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/19/85 thru 8/21/85:

Rig up & set cast iron bridge plug @ 10,250' and dump 35 ft. cmt on top of plug.  
Circulate hole with 10# salt gel.  
Set 100' plug (20 sks Class C cmt) @ 8363-8263'  
Set 100' plug (20 sks Class C cmt) @ 6311-6211'  
Rig up & attempt to shoot casing off @ 5300' - could not pull csg. Shoot casing off @ 4961'. Pull and lay down 4991' (119 jts) 5-1/2" 23# & 20# casing.  
Rig up & set 50 sks Class C cmt plug @ 5084'. Ran tbg & tag cmt @ 4712' (249' of cmt above cut off & 123' of cmt inside 5 1/2" csg).  
Set 100' plug @ shoe of 9-5/8" casing (csg set @ 4160') @ 4200'. w/50 sks Class C cmt.  
Tag top of plug @ 4,060'.  
Set 100' plug @ 1875-1775' w/50 sks Class C cmt.  
Set 100' plug (50 sks Class C cmt) @ 400-300' (13" csg set @ 366')  
Set 10 sks cmt @ surface and install dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jackie Midkiff TITLE Jackie Midkiff/Prod. Clerk. DATE 8/27/85  
APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE APR 6 1988  
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 30 1985

O.C.  
HOBBS OFFICE