		7	•	•	·-	C 103	
NO. CT COPILS	MECENTR	-				C+103 sedes Old	
DISTRIBU	TION	4				and C-103	
SANTA FE		NE'	M MEXICO OIL CONS	ERVATION COMMISSION	Effec	ilva 1-1-65	
FILE					_		
U.S.G.S.		7			Sa. Indica	ato Type of Lease	
LAND OFFICE	=	1			State	Fee	, [_]
ļ		1			5. State (Oil & Gas Lease No.	
OPERATOR		ل			V F1	0.0	
						mmmill.	m
	SUND	RY NOTICES	AND REPORTS ON	WELLS	(////)		/////
(CO NOT	USE THIS FORM FOR PR	TION FOR PERMIT -	" (FORM C-101) FOR SU	BACK TO A DIFFERENT RESERVOIR. TH PROFOSALS.)		777777777	7777
1.					7. Unit A	greement Name	
CIL X	GAS WELL	OTHER+					
2. Name of Opera	ator				8. Farm	or Lease Name	
Dalco	Oil Compan	11/			Roll	-17-State	
3. Address of Op		<u>y</u>			9, Well N	- 17-5 Ca CC	
				T 70701		-	
		W. lexas	- Midland,	lexas /9/01		and Pool, or Wildcat	
4. Location of W	ell				i	•	
UNIT LETTER	G	1980,	FROM THE North	LINE AND 1980 FE	EET FROM Wild	cat	
ONIT CELLER					IIII .		(1111)
F	ast	17	16-5	RANGE 33-E	NIMPM:	///////////////////////////////////////	/////
THE	LINE, SECT	ION	TOWNSHIP	RANGE	MMAW. //////		[[[]]
mmm	mmm	mmi.	Elevation (Show whather	DF RT. GR etc.)	12, Coun	amilility	444
		//////		, M., ON, COO,	1.	' (((((((((((((((((((((((((((((((((((((/////
	711111111		4240.3 GL		<u> Lea</u>		7777
15.	Check	Appropriate	Box To Indicate I	Nature of Notice, Report	or Other Data	· •	
		INTENTION T			QUENT REPOR		
	NOTICE OF	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
				REMEDIAL WORK	\Box	ALTERING CASING	
PERFORM REMED	IAL WORK		PLUG AND ABANDON	` -	H	•	片
TEMPORASILY AS	ANDON		<u></u>	COMMERCE DRILLING OPHS.		PLUG AND ABANDONME	ENT []
PULL OR ALTER	CASING		CHANGE PLANS	CASING TEST AND CEMENT JOB		. 57	ГØ
,				OTHER Ran Log	<u>s - Plug B</u>	ack Plugs	<u>[]</u>
GTHER PY	rep to run	5½" casin	gX				
			 			Jun of starting and p	rovocad
17. Describe Pro work) SEE (Operations (Clear	ly state all pertinent de	tails, and give pertinent dates,	including estimated	date of starting any fr	Toposeu
a only one							
0-27-75	TD 13,692'	sand, 1	ime, shale				
	Ran Dual L	aterolog	w/RXO & Com	pensated Neutron	Density L	ogs. Set t	hree
	Plugs as f		W/ KNO & CO			- J - ·	
	riugs as i	UTTOWS.					
	1001 1	(70 000	E70\/2E	Class BUB U/ 2	af 10 UD /	/ a b a a . C b a .	1
* *	122' plug	(13,692-1)	5/U) W/35 SX	Class "H" W/.3 5 sx Class "H" w/	01 1% HK-4	(above Stray	wn)
	261' plug	(13,010-)	12,749') w/7	5 sx Class "H" W/	.3 Of 1% H	R-4(across /	Atoka
·	174' plug	(11,710-	536') w/50 s	x Class "H" w/.3	of 1% HR-	4(across Che	ester
	, ,					!	Miss
	Prep to L[DP and r	un 5½" casin	a.			
				5 ·			
				<u>.</u> *			
		•					
		•					
	•						
	•						
10 26 75	Vanhal anni	anual fra	m lohn Dunya	n to John Kelley	for nlug	back	
10-20-75	vernal appr	ovar iro	m oomi Kunya	ii to oomi kerrey	ioi prag	Duck.	
18. I hereby cer	tify that the informati	on above is frue	and complete to the best	of my knowledge and belief.			
	(x, y, y)					10 0 =	
4151153	" N 77	inder	TITLE Di	vision Geologist	DATE	10-27-75	
3167110							
	· · · · · · · · · · · · · · · · · · ·	Bergest				OCT 29 197	75
					A.**	CAL PO IOI	
APPROVED BY	ldam e	es Bupts	TITLE		DATI	·	

CONDITIONS OF APPROVAL, IF ANY: