

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| | |
|---|------------------------------|
| 5a. Indicate Type of Lease | |
| State <input checked="" type="checkbox"/> | Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. K-4619 | |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | | |
|--|--|--|
| 1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- | | 7. Unit Agreement Name |
| 2. Name of Operator K. K. Amini | | 8. Farm or Lease Name Pennzoil "33" State |
| 3. Address of Operator P. O. Drawer 3068, Midland, Texas 79701 | | 9. Well No. 1-Y |
| 4. Location of Well UNIT LETTER 0 660 FEET FROM THE South LINE AND 2020 FEET FROM THE East LINE, SECTION 33 TOWNSHIP 16S RANGE 34E NMPM. | | 10. Field and Pool, or Wildcat Vacuum Gray-S.A. |
| 15. Elevation (Show whether DF, RT, GR, etc.) 4079.8' GL | | 12. County Lea |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 12/12/75 - Set CIBP plug @ 4625'.
- 12/13/75 - Pulled 26 jts. (1055.18) 4 1/2" casing, set CIBP plug @ 4618; and dump 35' cement on top of plug.
- 12/14/75 - Run tubing.
- 12/15/75 - Spotted the following plugs: 45 sks. @ 1050'; 50 sks. @ 450'; pull tubing, cut well head off.
- 12/16/75 - Set 10 sks. top plug, dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| | | |
|--|-------------------|---------------|
| SIGNED  | TITLE Comptroller | DATE 12/31/75 |
| APPROVED BY | TITLE | DATE |
| CONDITIONS OF APPROVAL, IF ANY: | | |

RECEIVED

APR 17 1976

U.S. CONSERVATION COMM.
NORTH DAKOTA