

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-25031</u>
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <u>West Knowles</u>
8. Well No. <u>#5</u>
9. Pool name or Wildcat <u>Knowles Driskard West</u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator <u>Conoco Inc.</u>
3. Address of Operator <u>P.O. Box 460 - Hobbs, NM</u>
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>34</u> Township <u>16S</u> Range <u>37E</u> NMPM <u>Lea</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: <u>Repair Parted Prod. Casing</u> ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MUR. Install BOP. Use Bowen lead seal cementing type casing patch and 4-1/2" 11.6 # K-55 casing to repair part @ ±5900'.
2. Pump 1000 sx Class "H" cmt around casing bowl and up 4-1/2" x 7-7/8" annulus. Seal csg patch by pulling 20,000 lb over string weight. WOC 24 hrs.
3. Perf 8240-44, 56-64, 8280'-8320 w/2 JSF.
4. Acidize w/2310 gals of 15% HCl-NE-FE acid. Return to prod.
For further technical information contact Tom Poelens @ 397-5870.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lee O. Yarbrough John W. Baker TITLE Administrative Sup'r. DATE Sept. 13, 1989

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

SEP 18 1989