

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO

LC 054687

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N.M. Oil Cons. Division

P.O. Box 1980

Hobbs, NM 8824

8. FARM OR LEASE NAME

Hudson Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Maljamar Abo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 15 T-17-S R-35-E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
V-F Petroleum Inc.
3. ADDRESS OF OPERATOR
110 N. Marienfeld St., Ste. 580 Midland, TX 79701
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
From Maljamar go south 1.5 mile then east 1980'
1980' FSL + 1980' FWL
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) Plug back & Recomplete ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. 4/23/97 Mi workover rig. Pull all production equipment.
2. 4/25/97 Install BOP. Set CIBP @ 9,650' Dump 35' cement. Set CIBP @ 8,950' Dump 35' cement. Test CIBP, casing & BOP to 1500# 30 min. Perforate abo zone 8,874-8,912' with 23 holes.
3. 4/28/97 Acidize with 1750 gal
4. 4/30/97 Acidize with 4000 gal
5. 5/01/97 Return well to pumping
6. 5/02/97 Release workover rig

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Superintendent

DATE 5/13/97

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

RECEIVED
MAY 16 P 4 53
BUREAU OF LAND MGMT.
ROSWELL OFFICE

MAY 29 1997