

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-25230

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-2229

7. Lease Name or Unit Agreement Name

Phillips E State

8. Well No.
#24

9. Pool name or Wildcat
Maljamar Gb/SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER Injection

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook St., Odessa, TX 79762

4. Well Location
Unit Letter F : 1980 Feet From The North Line and 2180 Feet From The West Line

Section 14 Township 17-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4123' GL 4132.5' RKB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-27-90: RU Permian WS. Install BOP.
3-28-90: GIH w/3-7/8" bit, scraper & 2-3/8" tbg to 4377'. Drill out scale fill to 4586'.
3-29-90: Pump 2300 gals 20% NEFe HCl w/iron sequestering agent, 300# rock salt & 300 gals brine @ 3-4 BPM. Max press 5000#, ISIP 3800#, 15 min 3300#, Rate 2.8 BPM, Max press 4600#, Avg. 4000#. RU to flow & swab back 87 BW and acid.
4-2-90: Press. test csg to 500# for 30 min., OK. Remove BOP. NU wellhead.
4-4-90: Install BOP.
4-9-90: Locate hole in csg between 876' & 908'. Plug set at 1000'.
4-10-90: Spot 20 sx Howco Matrix cmt containing 15% microbond. Squeeze into leak @ 1500#. WOC min. 30 hrs.
4-12-90: GIH w/3-7/8" drill bit. Tag cmt @ 700'. Drilled out @ 970'.
4-13-90: GIH w/plastic coated tbg to 4310'. Circ annulus w/inhibited brine. Set pkr. Remove BOP. NU wellhead.
4-14-90: Injected 138 BW in 5 hrs @ 1000#. Job

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

complete.

SIGNATURE J. L. Maples TITLE Assist., Reg. & Pro. DATE 6/21/90

TYPE OR PRINT NAME J. L. Maples TELEPHONE NO. 367-1411

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: