Form 9-331 (May 1963) DEPARTMEN. OF THE INTERI GEOLOGICAL SURVEY	SUBMIT IN TRIPLY (Other instructions re- verse side) SUBMIT IN TRIPLY re- UCher instructions re- UCHOR Verse side) Form approved. Budget Bureau No. 42-R1424 5. LEASE DESIGNATION AND SERIAL NO. LC-054687
SUNDRY NOTICES AND REPORTS ((Do not use this form for proposals to drill or to deepen or plug b Use "APPLICATION FOR PERMIT" for such pr	ON WELLS 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL GAS WELL OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	8. FARM OR LEASE NAME
Petroleum Exploration & Development	
P. O. Box 2412, Midland, Texas 79702	9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any See also space 17 below.)	2 1 State requirements.• 10. FIELD AND POOL, OR WILDCAT
At surface	Undesignated Straw
660' FSL & 1980' FEL	11. SEC., T., B., M., OE BLK. AND
Section 15-T17S-R32E Lea County, New Mexico	SURVEY OR AREA
	15-T17S-R32E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, 4021.3' GR	I. STATE
	Lea N.M.
16. Check Appropriate Box To Indicate N	lature of Notice, Report, or Other Data
NOTICE OF INTENTION TO :	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATEB SHUT-OFF REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE	FRACTURE TREATMENT ALTERING CASING
SHOOT OR ACIDIZE X ABANDON*	SHOOTING OR ACIDIZING X ABANDONMENT*
REPAIR WELL CHANGE PLANS	(Other)
(Other)	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
11. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent proposed work. If well is directionally drilled, give subsurface locati nent to this work.) *	t details, and give pertinent dates, including estimated date of starting any tions and measured and true vertical depths for all markers and zones perti-
M.I. & R.U. D.A.&S. Well Service, Ra Correlation log from 11557'(PBTD) to Strawn zones 1 hpf with 3 1/8" select 11534',11531',11528',11516', 11514', 11460',11458',11452' and 11450' a to Otis MH 2 packer and 2 3/8" 4.7#, N8 bottom tbg at 11540'; acidized with 2.6 BPM @ 6100-6500 psi, ISIP 5500 p very slight show of oil and gas. Re- 5000 gals. 15% NE and 16 ball sealer ISIP 5750 psi, 5 min. SIP 5700 psi. slight show of oil and gas. Released Otis packer. W.I.H. with Western Co. bridge plug @ 11240' pressure tested Co. W.I.H. with dumpbailer and dumpe 11220'. Western Co. perforated Permo total of 16 holes with selective fir holes on 3-6-77. W.I.H. with 2 3/8"	an Western Co. Neutron-Casing Collar o 9500'. Western Co. perforated ctive fire casing gun at 11548', 11546 ,11482',11480',11478',11465',11462', otal of 16 holes on 2-21-77. WIH with 80, EUE tbg. Set packer at 11380', 2000 gals. 15% BDA by Dowell. A.I.R. psi on 2-24-77. Swabbed and tested -Acidized by Dowell on 3-1-77 with rs, A.I.R. 1.25 BPM @ 5600-5800 psi, Swabbed and tested well dry very d packer P.O.H. with 2 3/8" tbg. and . wireline and set Baker Model N d B.P. to 5000 psi, held O.K., Western ed 20' Class H cement on B.P., PBTD D-Penn zone 1 hpf 10840'-10856' a re 3 1/8" casing gun, 0.42" burrless tbg. and Otis MH2 packer. Set packer eparing to test and acidize Permo-Penn
18. I hereby covery that the foregoing is true and correct	
SIGNED . R. Sutherland TITLE Vi	ice President DATE 3-7-77
(This space for Federal or State office use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY :	ACCEPTED FOR RECORD

*See Instructions on Reverse Side

MAR

U. S. GEOLOGICAL SURVEY

HOBBS, NEW MEXICO