

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Drilling Well</u>	7. Unit Agreement Name
2. Name of Operator <u>David Fasken</u>	8. Farm or Lease Name <u>Whit Ingram</u>
3. Address of Operator <u>608 First National Bank Bldg.; Midland, Texas 79701</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>I</u> , <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>16-S</u> RANGE <u>38E</u> NMPM.	10. Field and Pool, or Wildcat <u>Undes. Garrett Drinkard</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3719 K.B.</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input checked="" type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Plug back &amp; drill around junk</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set 400 sxs. cement plug from 1240' up to 840'.
- W.O.C. 36 hrs.
- "Dress" top of cement plug.
- Drill off cement plug w/Dyna-drill.
- Drill 11" hole around 8-5/8" junk in old hole.
- Drill to 5000', set & cement 8-5/8" intermediate casing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert H. Angevine TITLE Agent DATE Sept. 16, 1977

APPROVED BY John Runyan TITLE Geologist DATE SEP 19 1977

RECEIVED

SEP 10 1977

OIL CONSERVATION COMM.  
HOBBS, N. M.