

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-26292
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. LG-3728 L-5464
7. Lease Name or Unit Agreement Name NM "34" STATE COMM.
8. Well No. 1
9. Pool name or Wildcat SOUTH SHOE BAR (ATOKA)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
2. Name of Operator FORCENERGY GAS EXPLORATION, INC.	
3. Address of Operator 2730 SW 3RD AVE., SUITE 800, MIAMI, FLORIDA 33129-2237	
4. Well Location Unit Letter <u>F</u> : <u>1980'</u> Feet From The <u>NORTH</u> Line and <u>1980'</u> Feet From The <u>WEST</u> Line Section <u>34</u> Township <u>16S</u> Range <u>35E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3980' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-25-96 SPOT 100 SX "H" NEAT CMT. 12,448' - 12,348'
- 1-26-96 TAG TOC 11,250'. OK'D BY GARY WINK, NMOC D CUT TBG @ 9360' OR FREE POINT.
- 1-26-96 CUT TBG LOAD HOLE, SPOT 25 SX "H" NEAT CMT 9360' - 9248'
- 1-29-96 CUT & PULL 5-1/2" CSG FROM 8820'
- 1-31-96 LOAD HOLE W/MUD SPOT 45 SX "C" CMT 8870' - 8770' 5-1/2" STUB.
- 2-01-96 TAG TOC 8750'. LOAD HOLE W/MUD. SPOT 35 SX "C" CMT 6253' - 6148' SPOT 45 SX "C" CMT 4906' - 4800' 9-5/8" SHOE.
- 2-02-96 TAG TOC 4792' LOAD HOLE W/MUD. SPOT 45 SX "C" CMT 478' - 370' TAG TOC 340' 13-3/8" SHOE.
- 2-02-96 SPOT 25 SX "C" NEAT CMT SURFACE PLUG.
- 2-05-96 REMOVE WELLHEAD & INSTALL DRYHOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry Murray TITLE AGENT DATE 2-6-96
TYPE OR PRINT NAME LARRY MURRAY TELEPHONE NO. (915) 683-9722

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

FEB 11 1997