## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

**District Office** OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM 88240 2040 Pacheco St. 30025-26350 Santa Fe. NM 87505 Indicate Type of Lease DISTRICT II P.O. Drawer DD, Artesia, NM 88210 STATE FEE State Oil & Gas Lease No. **DISTRICT III** 1000 Rio Brazos Rd., Aztec, NM 87410 Anti-Auto-Auto-A SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" MORTON SOLID STATE UNIT (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: MELL 🔀 OTHER ₅Well No. 2Name of Operator CONCHO RESOURCES INC 1 ∍Pool name or Wildcat 3Address of Operator TRES PAPALOTES PENN 110 W LOUISIANA STE 410; MIDLAND TX 79701 WEST 990 Feet From The NORTH Line and E\_\_\_\_: 2160 Feet From The \_\_\_ Unit Letter 1 FA County **NMPM 15S** Range 10Elevation (Show whether DF, RKB, RT, GR, etc.) 4119 GL Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11 SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING PLUG AND ABANDON REMEDIAL WORK PERFORM REMEDIAL WORK PLUG AND ANBANDONMENT COMMENCE DRILLING OPNS. CHANGE PLANS **TEMPORARILY ABANDON** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: ADD ADDITIONAL PAY/Squeeze Csg Leak OTHER: 12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 7-13-99 POOH w/ rods. 7-14-99 Set RBP @ 6398'. Test to 3100#. 7-15-99 RIH & set cmt retainer @ 5829'. Spot 75 sx C w/ 3/10% D-112 followed by 50 sx C neat to retainer and sting in. Pump @ 1/2 BPM & 1280# w/ 30 sx lead cmt past csg leak. Sqz w/ 80 sx cmt past hole in csg @ 3500#. 7-20-99 Old squeeze holes @ 5652 & 5680' - leaking. 7-21-99 Spot 75 sx C w/ 3/10% Halad 322 & 50 sx C Neet to 5000' in tbg. Sting in & squeeze @ 5652' & 5680' w/ 34 sx lead cmt to 3800#. 7-23-99 DO cmt from 5234-5625' & fell out of cmt. Circ clean & press test sqz to 1000 psi. 7-24-99 TIH & tagged fill & cmt above ret @ 5815'. DO cmt & cmt reg @ 5829; 7-26-99 DO cmt from 5830-5970'. Press test sqz to 1000 psi. Lost 100 psi in 30 mins. 7-28-99 Pump 30 sx Micro Matrix cmt from 6000-5720'. Pressure annulus to 500 psi. Hesitate squeeze holes from 5948-5978'. Obtained 3000 psi squeeze & held. Had 5 bbls slurry in csg. Pumped 1 bbl away @ 5 BPM before squeeze obtained. 8-2-99 WIH w/ 4-3/4" bit, DC, & 2-7/8" tbg. Tagged cmt @ 5750'. Drilled cmt from 5750-5980'. Test to 1000 psi. Rel RBP & POOH. 8-4-99 TIH w/ 4-5/8" bit, DC & 2-7/8" tbg. Tagged fill @ 10,398'. CO fill from 10398' to 10456'. TOH. continued on page 2 above is inte and complete to the best of my knowledge and belief. I hereby certify that the TITLE PRODUCTION ANALYST DATE 08-31-99

(This space for State Use)

SIGNATURE

Orig. Signed by, Paul Kautz Geologist

SEP 07 1999

TELEPHONE NO. 915-683-7443

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

TYPE OR PRINT HAME TERRI STATHEM