

RECEIVED

JUL 23 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

HYDROSTATIC PRESSURE TEST - B.O.P.'S

HONDO DRILLING - HONDO FEE #1

HONDO DRILLING - RIG 4

JULY 15, 1979

by

YELLOW JACKET TOOLS AND SERVICES, INC.

CARLSBAD, NEW MEXICO

TESTED BY: GARY ALLISON

TICKET NO. 3246

RECEIVED
JUL 24 1973
O.C.D. HOBBS, OFFICE

RECEIVED
JUL 24 1973
O.C.D. HOBBS, OFFICE

July 18, 1979

Hondo Drilling
P. O. Box 116
Midland, Texas 79701

Gentlemen,

We made a hydrostatic pressure test on your Hondo Fee #1, located in the Carlsbad, New Mexico area, in the Midland, Texas district on July 15, 1979.

Test was made using (plug) _____ or (packer) x or (both) _____.

When we arrived, the rig was ready

These changes were made to BOP hookup since previous test none.

List any delay observed to operation of BOPs during test: and, loss of closing pressure (other than hydril test) _____ (Corrected) _____.

List items replaced during testing: _____.

Closures were made using pump _____ accumulators both x with observed pressure of 2500 for test to ram type BOPs and 1500 for test on Hydril.

Accumulator bottles 5 were pressured to 1500 at end of test.

Control valves operating as indicated on closing unit manifold except: _____.

Extensions were _____ or were not _____ hooked up to BOPs at end of test.

No test desired to blind rams hydril kelly cock and safety valve.


Items leaking at the conclusion of testing and/or malfunction of BOPs at end of test: _____.

A tracing of surface control equipment has been prepared to show any leaks and malfunctions. A report taken from field notes and a pressure chart of the test are also enclosed.

Your comments and suggestions will be appreciated.

Sincerely yours,

Verdine Jacket Tools and Services, Inc.


Bill Ouff

cc: [unclear]

RECEIVED
JUL 24 1979
O.C.D. HOBBS, OFFICE



COMPANY HONDC DRILLING

well HCND0 FEE 1

Date 7-15-79

[illegible]




RECEIVED
JUL 24 1973
O.C.D. HOBBS OFFICE

BLOWOUT CONTROL EQUIPMENT.....HONDO DRILLING.....HONDO FED #1



Hydril
5000
NTD

LEAKS



7-5000 Cameron

ITEMS LEAKING
NTD NO TEST DESIRED
(R) ITEMS REPLACED




Items leakign DURING testing
7-15-79

BLOWOUT CONTROL EQUIPMENT.....HONDO DRILLING.....HONDO FED #1



Hydril
5000
NTD

LEAKS




10-5000 Cameron

ITEMS LEAKING
NTD NO TEST DESIRED
(R) ITEMS REPLACED

No visible leaks at
CONCLUSION of testing
7-15-79

RECEIVED
JUL 24 1973
O.C.D. HOBBS. OFFICE



RECEIVED
JUL 24 1973
O.C.D. HOBBS, OFFICE