

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-9380	
7. Unit Agreement Name	
-	
8. Farm or Lease Name	
Texaco State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Wildcat	
11. Elevation (Show whether DF, RT, GR, etc.)	
4291 Gr.	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPLEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/>	CAS WELL <input type="checkbox"/>	OTHER- Wild Cat Well
2. Name of Operator		
D. E. Radtke & Associates, Inc.		
3. Address of Operator		
P. O. Box 1703, Midland, Texas 79702		
4. Location of Well		
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 15 TOWNSHIP 15 S RANGE 32 E N.M.P.M.		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/13/80-M.I.R.U. H.D. Oden Csg. pullers.

5/14/80-Shot 5½" csg. at 6600, would not come.

5/15/80-S.D. A/C Weather.

5/16/80-Shot 5½" csg. at 6150, would not come.

5/17/80-Shot 5½" csg. at 5980-Pulled & lay down 2360'.

5/20/80-Finished pulling and laying down 5½" csg. (5980').

Ran in w/ 2 3/8" tbq. to set plug. Could not get past 4138'.

5/21/80-Worked all day trying to get below 4138'.

5/22/80-Made up spear and tried to dislodge or retrieve obstacle at 4138'.

5/23/80-Received Verbal approval from Jerry Sexton O.C.D. to plug.

100' below and 100' up into 8 5/8". Field inspector was on location.

5/24/80-Set cement plugs 100'below and 100' into 8 5/8" (4110').

Set 100' cmt. plug at 1600-10 sax at surface w/surface marker 4'above ground.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Com Barry TITLE Agent DATE 6/4/80

APPROVED BY Al Sutton TITLE Oil & Gas Inspector DATE May 9 1981

CONDITIONS OF APPROVAL, IF ANY: