3959

All distances must be from the outer boundaries of the Section. Well No. rated Dinero Operating Company Eidson Section Township fignae to better 20 16 S 35 E Lea Н tur Footage Location of Well: 660 East North feet from the line and Dedicated Acreage: · ilevel Elev. Producing Formation Pool Morrow Wildcat 320 4011' t. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below. 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and rovalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc? If answer is "yes," type of consolidation _ If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.). No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commis-CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief. 1980' Production Secretary 660' Dinero Operating Co. #1 February 21, 1980 DINERO OPERATING CO. 320 ACRES ay this platinds played from field T-16-S scrupt stevers blade by me or R-35-E and/or Land Surveyor Certificate No.

2000

1320 1650

1980 2310

1500

1000

500

OIL CONSERVATION DIV.

08. SS HAL

BECEINED