

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-025-26937 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. V-122 |
| 7. Lease Name or Unit Agreement Name Lovington 29 State |
| 8. Well No. 1 |
| 9. Pool name or Wildcat Northeast Lovington Penn |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|---|
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 2. Name of Operator Harvey E. Yates Company |
| 3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88202 | 4. Well Location Unit Letter <u>D</u> : <u>510</u> Feet From The <u>North</u> Line and <u>660'</u> Feet From The <u>West</u> Line Section <u>29</u> Township <u>16S</u> Range <u>37E</u> NMPM <u>Lea</u> County |

| |
|---|
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3814.3' GL (15' KB) |
|---|

| | |
|--|--|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/> | SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set CIBP @ 11,000' w/35' cmt on top
- Spot 200' plug @ 7,647', 6300', 5950', 4400, & 2050'
- Pull 660' 5 1/2" csg.
- Spot 20 sx plug @ 950'
- Spot 50 sx plug @ 710' and tag @ 590'
- Spot 45 sx plug @ 400'
- Spot 35 sx plug @ 100'
- Install dry hole marker (3-12-90) and clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tim W. Gum TITLE Engineer DATE 3-15-90

TYPE OR PRINT NAME Tim W. Gum skh TELEPHONE NO. 623-6601

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: