NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CON	NEW MEXICO OIL CONSERVATION COMMISSION	
FILE			Effective 1-1-65
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5. State Oil & Gas Lease No.
			E 1075
SUNDRY NOTICES AND REPORTS ON WELLS			
USE "APPLIC	ATION FOR PERMIT -" (FORM C-101) FOR SU	CH PROPOSALS.)	
OIL CAS WELL	OTHER-		7. Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
V-F Petroleum Inc.			ARCO State
3. Address of Operator			9. Well No.
One Marienfeld Place, Suite 580, Midland, Texas 79701			1
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM			Dean-Devonian
THE West LINE, SEC	TION 35 TOWNSHIP 15-S	5	.em. [[]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]]
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	15. Elevation (Show whether	DF. RT. GR etc.)	
	3863 GR	.,,,	12. County
$\frac{1}{16}$			Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:			
		SUBSEQUE	ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	. – – –
TEMPORARILY ABANDON			ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
		CASING TEST AND CEMENT JOB X	r Flow
OTHER	[]	OTHER JAIL WALE	<u>X</u>
17. Describe Proposed or Completed (work) SEE RULE 1103.	Operations (Clearly state all pertinent det	ails, and give pertinent dotes, includ	ding estimated date of starting any proposed
 Spudded well 11 a.m. 10-7-80 & drld 17-1/2" hole to 347'. 10-8-80 set 347' of 12-3/4 48# X-42 csg & cemented w/400 sx Class C 2% CACL & circulated 			
cement to surface.			
3. Nippled up Hydril & Schafter BOPS. Tested casing to 1000 PSI for 30", pressure held.			
4. 10-8-80 to 10-11-80 drld 11" hole to 2673' and encountered very severe water flow from			
charged up salt formation. Pumped in 400 bbls 17#/gal mud, followed by 3000 sx Class H			
2% CACL in an attempt to cement drill string to shut off water flow. This attempt			
unsuccessful. Had water flow in shot hole 185 yds NE of rig when drilling well tempo-			
rarily SI. After reopening drilling well, water flow in shot hole quit. Moved in			
Sumruld Drlg. Service & cleaned out shot hole to 273' in red bed. Circulated hole w/400			
sx in several stages down 2" pipe. Left 2" pipe in hole, pumped 200 sx down 2", displace			
all coment out of	$f 2^{\mu}$ and loft 2^{μ} onon as	2 pipe in noie, pumpe	Bu 200 SX QUWN 2°, GISPIACE
Owner A second	f ² " and left ² " open as	per instructions from	mr. Alexander, Surtace
Owner. A second shot hole that erupted briefly never did flow after drlg well was opened back up. Plans are to plug this 2nd shot hole immediately.			
5. 10-13-80 After flow decreased, installed drilling head & drilled 11" hole to 4927'			
while well was -1	nuw decreased, installed	uriling nead & dril	iea II" noie to 492/"
while well was allowed to flow salt water into lined pits.			
6. 10-18-80 Ran Fluid Caliper by Permian Fluid Caliper Service & found that red bed & salt			
section were not badly washed out (2521 cuft annular vol.)			
7. 8-19-80 Ran 8-5/8" casing to 4876'. Ran Lynes ECP (Packer) 2058' and DV tool @ 2022'. 16. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
8. I hereby certify that the information	above is true and complete to the best c	f my knowledge and belief.	reinueu un raye z
15415.	Λ		·
IGNED // - + Mare	to	President	DATE 10-30-80
Usy Could be			
			DATE
ONDITIONS OF APPROVAL, IF ANY	1		

مىمەر يە