

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Sun Oil Company - Midland	8. Farm or Lease Name Maymie Lewis
3. Address of Operator P.O. Box 1861, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>0</u> <u>330</u> FEET FROM THE <u>South</u> LINE A <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>6</u> TOWNSHIP <u>14-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3816.4 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING O.V.S. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-20-81 - Jerry Saxton, NMOGC, Hobbs: Verbal P&A instructions: After cut off 5 1/2 csg. spot 100' cmt plug at stub, 100' cmt plug above salt section (rustler 2170 by Sunmark Geol.) 2050-2150 and 10 sx at surface w/marker/

MIRU, Dig out cellar, remove wellhead. Weld on 5 1/2 pull nipple, install Hyd Jacks, worked 5 1/2 csg, ran free point, 10% free 3700, 20% 3680, 100% free 3600, load 5 1/2 csg w/20 bbls salt water, cut 5 1/2 csg at 3630, worked stuck pipe, pres to 2000, circ 50 bbls wtr, worked 5 1/2 csg free w/200000# pull, pull 3630' 5 1/2 csg. Ran 2 3/8 tbg open ended to 3680, circ hole w/150 bbls salt gel mud, spot 40 sxs cmt plug 3680-3520, raise tbg 2150, spot 40 sxs cmt plug 2150-2020, POH w/tbg/ Remove BOP and wellhead. (Dug out cellar 5' below gro) Cut off wellhead/ Spot 20 sxs plug at surface/ Install steel plate and dry hole marker/RR at 11 AM 7-23-81/ P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Maria L. Perez TITLE Sr. Accounting Assistant DATE 7-30-81
APPROVED BY Ronald M. [Signature] TITLE OIL & GAS DIRECTOR DATE SEP 5 1981
CONDITIONS OF APPROVAL, IF ANY: