

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease

State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO UPERIN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name Maymie Lewis
3. Address of Operator P. O. Box 1861 - Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER 0 330 FEET FROM THE South LINE AT 2310 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 14 S RANGE 38 E N.M.P.M.	10. Field and Pool, or Wildcat Wildcat
11. Elevation (Show whether DF, RT, GR, etc.) 3816.4 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING O.P.S. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	Run Surface Casing <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud 9 pm 11-6-80
DRILLED 348' IN RED BED. NU BOP, RAN & CEMENTED 13-3/8" CASING WITH 400 SX CLASS C 2%
CACL, 1/4# FCL CIRCULATE 75 SX. RESUME DRILLING 2 JTS DP STUCK W/BIT @ 1476. PUMPED
INTO FORM @ 1400 PREP TO SPOT OIL TO FREE DP. JARRING ON STUCK DP W/DRIVING TOOL, SPOT
50 BBLS LSE OIL. NO MOVEMENT AFTER 4 1/2 HRS. RAN FREE POINT, INDICATED 90% STUCK @ 720',
100% FREE @ 708'. RIGGED UP DRLG TOOL JARRED 4 1/2" IN 1 1/2 HRS. JARRED & LOWERED DP 9' IN
22 HRS. NO FREE TRAVEL NO UPWARD MOVEMENT W/40,000# OVERPULL. RUN WASH PIPE & DC, DRIVE
ON STUCK DP 5 1/2 HRS LWRD 3" UNABLE TO CIRCULATE. RAN FREE POINT STUCK 718'. POH RAN
10-1/8 SHOE 6 JTS. 9-5/8" WASH PIPE & 9 DC TO WASH OVER FISH, WASHED OVER FISH 693-876
POH. SCREW INTO FISH JARRED & ATTEMPT TO DRIVE, MOVED UP HOLE 9'. FREE POINT INDICATE
50% STUCK @ 1247 FREE @ 1230. PREP TO POH. WASHING OVER 9" DC @ 1265 PULLED & RECOVER
DC & 1 JT DP. TOP OF FISH @ 1223, WASH OVER FISH CIRC 1 HR START OUT HOLE. WP STUCK
@ 1390 WORKED & CIRC LOOSE. CIRC COND MUD 21 HRS CLEANED UP HOLE. POH W/WP LEFT BTM
1/4 SHOE IN HOLE RAN 11 1/4 SKIRTED SCREW IN SUB WASHED RED BED 1195-1227 SCREWED INTO
FISH. POH.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Louis Williams TITLE Sr. Accounting Assistant DATE 11-20-80

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: