

UNITED STATES
DEPT. OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR
(Other instructi
verse side)

CATE
on re

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-029405(A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA Unit Bty 2

9. WELL NO.

360

10. FIELD AND POOL, OR WILDCAT

Mabamar 6/5A

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 20-175-32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS 88240

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit H

899'

891' FEL & 2371' FNL

14. PERMIT NO.

30-025-27063

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) temporary abandon

REPAIRING WELL


ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- MIRU on 7-25-86. POOH w/ pump & rods. Stung into pkr @ 3900' & pump'd 33 sxs class "c" neat. Spot 7 sxs sand on top of pkr.
- Spotted 60 sxs class "c" from 3860'-3642'. Tag TOC @ 3492'. Press. test backside to 500psi. held. Set cmt ret @ 3247'.
- Spotted 100 sxs class "c" neat. Set pkr @ 3245'. Spotted 30 sxs class "c" on top of pkr. Tag cmt @ 3129'. Rig down on 8-5-86.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE

8-27-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

SEP 03 1986

*See Instructions on Reverse Side

RECEIVED
SEP 8 1986
D.C.C.
HOBBS OFFICE