

TAYLOR B-2
Maljamar Field

Supplement to Well Completion Report
HLX-53 Treatment - Cost \$622.

CHRONOLOGICAL HISTORY

2-17-66 Dumped 750 gallons Kerosene and 4 gallons Hyflo down annulus and circulated 14 hours with well pump.
2-18-66 Turned to battery for 20 hours.
2-19-66 Mixed 30 gallons HLX-53 with 72 BFW and flushed with 105 BFW. Pressure reached 1200 psi on flush. Let set 1 hour and placed well on production.


PRIOR PRODUCTION

November 1965:	75 BOPD and 1 BWPD
December 1965:	88 BOPD and 2 BWPD
January 1966:	109 BOPD and 1 BWPD
February 1966:	111 BOPD and 1 BWPD

AFTER TREATMENT

Well production jumped from 110 BOPD and 1 BWPD to 121 BOPD and 1 BWPD.

March 1966 production averaged 123 BOPD and 1 BWPD.



J. D. WEBB

JDW/cz

copy CNS 4-22-66