

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LC 4193	
7. Unit Agreement Name	
8. Farm or Lease Name	
state 23	
9. Well No.	
1 # 1	
10. Field and Pool, or Wildcat	
Grasslands	
12. County	
Lea	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT L" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator  
M & W of Lovington, Inc.

3. Address of Operator  
Box 922, Lovington, N.M. 88260

4. Location of Well  
UNIT LETTER K 1980' FEET FROM THE South LINE AND 1980' FEET FROM  
THE West LINE, SECTION 23 TOWNSHIP 15S RANGE 34E N.M.P.M.

11. Elevation (Show whether DF, RT, GR, etc.)

12. County  
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Cancel plug &amp; abandon &amp; except</u> <input checked="" type="checkbox"/>	
		remedial work.	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Fish Rods
2. Pull and change out rods to combination 1", 7/8" & 3/4" string.
3. Pull tubing
4. Run tubing back and change out top 4000' to 2-7/8"
5. Run rods and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Bernice J. Sexton* TITLE Prod. Clerk DATE 6/10/84

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUN 26 1984

RECEIVED  
JUN 22 1984  
O.C.  
HOBAS - 6