

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LC - 4193	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator ARGONAUT ENERGY CORPORATION		8. Farm or Lease Name STATE "23"
3. Address of Operator P. O. Box 4060, Amarillo, Texas, 79116-4060		9. Well No. No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>23</u> TOWNSHIP <u>15S</u> RANGE <u>34E</u> N.M.P.M.		10. Field and Pool, or Wildcat Grassland - WC
15. Elevation (Show whether DF, RT, GR, etc.) 4067.7 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @ 10,250' w/35 cement cap. Load well with Mud fluid.
Set 100' plug @ top Wolfcamp @ 9,673'.
Set 100' plug @ top Abo @ 8,067'.
Set 100' plug @ top Tubb @ 7,321'.
Set 100' plug @ top Glorietta @ 6,060'.
Set 100' plug @ 8 5/8" shoe @ 4,600'.
Set 100' plug @ 4 1/2" Stub (11.6-13.5# pipe).
Set 100' plug @ top Salt @ 1,795'.
Set 100' plug @ 350' - 13 3/8" shoe.
Set 10 sacks cement @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BILLY D. JOHNSON

SIGNED

TITLE Dir. & Prod. Supt.

DATE 12/5/83

ORIGINAL SIGNED BY JERRY SEXTON

PROVED BY DISTRICT 1 SUPERVISOR

NOTATIONS OF APPROVAL, IF ANY:

TITLE

DATE

DEC 7 1983