State of New Mexico and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I	OIL CONSERVATION	ON DIVISION	NC					
P.O. Box 1980, Hobbs, NM 88241-1980	2040 South Pacheco Santa Fe, New Mexico 87505			well api no. 30-025-27283				
DISTRICT II 811 S. First Street, Artesia, NM 88210				5. Indicate Type of Lesse	STATE	X	FEE	
				6. Stata Oil & Gas Lease No.				
DISTRICT III 1000 Rio Brazos Rd., Aztac, NM 87410				K-6874				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lesse Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR DIFFERENT	FROPOSALS TO BRIDGE OR TO DELLE OR OF THE PERM (FORM C-101) FOR SUCH PROPOSALS.)	IIT"						,
1. Type of Well: OIL GAS				NORTHEAST KEM	INIT7			
WELL WELL	X OTHER			8. Well No.				
Name of Operator ELK OIL	COMPANY			6		<u>.</u> .		
3. Address of Operator			00000 0040	9. Pool Name or Wildest	MOLECA	MD		
POST O	FFICE BOX 310, ROSWELL, NE	W MEXICO	88202-0310	KEMNITZ LOWER	VVOLFCA			
Unit Letter N	: 660 Feet From The	SOUTH	Line and	1980 Feet	From The		EST	_ Line
Section 9	Township 16 SOUTH		Range 34 EA	ST NMPM	LEA		County	
	10. Elevation (Show wh 412	uether DF, RKB, RT, O' GR	, GR, etc.)					
11.	Check Appropriate Box to I	ndicate Nati	ure of Notice, Rep	ort, or Other Data				
NOTICE OF	INTENTION TO:		;	SUBSEQUENT REP	ORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	X	altering cas	ING		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	G OPNS.	LUG AND ABA	ироиме	NT	
pull or alter casing			CASING TEST AND CE	MENTJOB				
OTHER:			OTHER:					
12. Describe Proposed or Completed Operations (Clearly state all pertinent data)s, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 MARCH 3RD THRU MARCH 13TH, 2001: RIG UP PULLING UNIT, PULL OUT OF HOLE WITH TUBING AND PACKER. RUN IN HOLE WITH BP, SET AT 10,920' TO ISOLATE CISCO PERFORATION'S. PULL OUT OF HOLE. RUN IN HOLE WITH PERFORATORS, PERFORATE 10,684'-10,699', 18 HOLES. PULL OUT OF HOLE. RUN IN HOLE WITH TUBING AND PACKER. SET PACKER AT 10,586'. ACIDIZE PERS WITH 2000 GALLONS HCL. RIG UP SWAB, SWAB BACK LOAD. PULL OUT OF HOLE WITH TUBING AND PACKER. RUN IN HOLE WITH TUBING AND RODS. PUMPED 22 OIL, 47 LOAD WATER, 44 MCF GAS. MARCH 16, 2001: TESTED - MADE 22 OIL, NO WATER, 50 MCF GAS.								
	_			00h				
I hereby certify that the information above	se is true and complete to the best of my knowledge and b			ART	13/3	_	100:5	
SIGNATURE	TITI	LE PRES	SIDENT		DATE		/28/0	
TYPE OR PRINT NAME	OSEPH J. KELLY			TELEPHO	NE NO	505-6	23-319	JU
(This space for State Use)			Orig. Sign Paul K	ed DF autz	DATE	·		
APPROVED BY CONDITIONS OF APPROVAL, IF AN	Y:	LE	Geolog			· `——	<u> </u>	

2A Kennita Cisco