

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-2229

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator	8. Form or Lease Name
Southland Royalty Company	Malmar Unit Tr. 1
3. Address of Operator	9. Well No.
21 Desta Drive, Midland, Texas 79701	9
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>B</u> <u>20</u> FEET FROM THE <u>North</u> LINE AND <u>1365</u> FEET FROM	Malmar (GB-SA)
<u>East</u> THE <u>13</u> LINE, SECTION <u>17S</u> TOWNSHIP <u>32E</u> RANGE <u>32E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4232.8' GR	Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
OTHER ☐			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. GIH w/RBP, pkr & tbg. MIRUPU. POH w/rods & BHP. Tag btm w/tbg. Tally out of hole. Checked fill @ 4502'. No indication of scale on rods or tbg.
2. RU to swb. TIH w/RBP & RTTS pkr & tbg. Set RBP @ 4483'. GIH w/tbg. Spot 100 gals 15% NE FE HCl 4480-4450'. Set pkr @ 4416'. Pmp acid away 250 gals 15% NEFE HCl acid.
3. Swbd 15 BLW, 55 BW & 1 BO in 4 hrs. Release pkr. Pull RBP to 4425'. Spot acid from 4386-4350'. Pull pkr to 4355'. Trt perfs 4374-78' w/250 gals 15% NEFE acid @ 2 BPM 2800#. Flw & swb 31 BLW, 3 BW & 1 BO w/good show of gas. Release pkr. Move RBP to 4340'. Spot acid from 4310'-4240'. Pull pkr to 4190'. Acdz perfs 4243-4304' w/1500 gals 15% NEFE acid & 60 Ball Sealers.
4. GIH w/rods & BHP. Swbd 72 BLW, 6 BW & 1 BO. POH w/tbg, pkr. Ran 2 3/8" tbg. Set @ 4488'. SN @ 4460'. Pmpd 170 BW in 21 hrs. Ran rods & BHP. Start well pmpg.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED F.N. RAD by D. Roberts TITLE District Operations Engineer DATE 1/21/83

APPROVED BY ORIGINAL SIGNED BY EDDIE W. SEAY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 25 1983

RECEIVED

JAN 24 1983

G.C.D. 1983
HOBBS OFFICE