

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fed <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-8295	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name Lea "AAK" State
3. Address of Operator P. O. Box 670, Hobbs, NM 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>0</u> , <u>1980</u> FEET FROM THE <u>East</u> LINE AND <u>3300</u> FEET FROM THE <u>South</u> LINE, SECTION <u>6</u> TOWNSHIP <u>16S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 4377' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with tubing. Set CIBP at 9925', test 1000#. Cap with 35' cement. Cut off casing 10' above free point. POH with casing. GIH with open-ended tubing to 9880'. Circulate hole with abandonment mud. Spot 50' cement plug inside and 50' cement outside 5½" casing. Spot 100' cement plug 8978'-8878', 7642'-7542', 6875'-6775', 5686'-5586' and 5000'-4900'. Spot 10 sack surface plug. Erect dry hole marker. Clean and clear location as required

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R.D. Pite</u>	TITLE <u>Area Engineer</u>	DATE <u>3-1-82</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT SUPERVISOR		
APPROVED BY <u>JERRY SEXTON</u>	TITLE <u>DISTRICT SUPERVISOR</u>	DATE <u>MAR 2 1982</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAR -1 1982

**O.C.D.
HQSAS OFFICE**