## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

and and annual and a	 
NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.3.0.3.	
LAND OFFICE	
0.000	

## OIL CONSERVATION DIVISION

DISTRIBUTION	1		
	Р. О. ВОХ	2088	Form C-103 Revised 10-1-78
ANTAFE	SANTA FE, NEW	MEXICO 87501	.kevised 10-1-78
ILE			Sa, Indicate Type of Lease
.3.0.3.			State X Fee
AND OFFICE			
PERATOR			5. State Oil & Gas Lease No.
			OG 5119
SUNI POR MENT JE THIS FOR FOR JOE TAPPLIC	DRY NOTICES AND REPORTS ON V	WELLS ck to a different hesenvoir, propusals.)	
L X GAS	OTHER-		7. Unit Agreement Name
of Operator			8. Farm or Lease Name
	on		Lea "LL" State
as of Operator			9. Well No.
O. Box 670. Hobb	os. NM 88240		1
Ion of Well			10. Field and Pool, or Wildcat
T LETTER F	2100 FEET FROM THE North	LINE AND 1980	Maljamar Maljamar
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
3898' GL		Lea	
Chec	k Appropriate Box To Indicate Na	ature of Notice, Report or O	ther Data
			IT REPORT OF:
M REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING PLUG AND ABANDONMENT
ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
R		OTHER	
	SUNI  (DO NOT USE THIS FORM FOR USE "APPLICATION"  (DO NOT USE THI	SUNDRY NOTICES AND REPORTS ON A SUNDRY NOTICES AND REPORTS ON A SUNDRY NOTICES AND REPORTS ON A USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH OTHER-  of Operator  alf Oil Corporation  as of Operator  Q. Box 670, Hobbs, NM 88240  lon of Well  TLETTER F 2100  FEET FROM THE NOTTH  West LINE, SECTION 32 TOWNSHIP 17S  Check Appropriate Box To Indicate Na NOTICE OF INTENTION TO:  WEST PLUG AND ABANDON ARILLY ABANDON  ARILLY ABANDON  ALTER CASING CHANGE PLANS	SUNDRY NOTICES AND REPORTS ON WELLS  TOO NOT USE THIS FORM FOR PROPOSALS TO CRILL ON TO OCCUPIN ON PLUG DACK TO A DIFFERENT RESERVOIR.  TOO NOT USE THIS FORM FOR PROPOSALS TO CRILL ON TO OCCUPIN ON PLUG DACK TO A DIFFERENT RESERVOIR.  THERE  OTHER-  OF OPERATOR  OTHER-  OF OPERATOR  OF DESTROY  ASS OF OPERATOR  OTHER-  OTHER-  OF OPERATOR  OTHER-  OF OPERATOR  OTHER-  OTHER-

TD 6:30 P.M., 11-2-81; logs through 4:00 P.M., 11-3-81. RU & ran 105 joints  $5\frac{1}{2}$ ! 15.5# K-55 ST&C (4191') set at 4200'. Cement with 1010 sacks Gulfmix & 740 sacks poz. Plug down 6:30 A.M., 11-4-81. WOC 18 hours. Circulate cement to surface. Test casing 1000#.

8. I hereby certify that the information above is true and	complete to the best of my knowledge and belief.	
IGNED FRM authous	TITLE Area Drilling Superintendent	DATE 12-7-81
Orig. Signed by Les Clements	TITLE	DEC 8 1981
OIL & GOS TISPE		