

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Tenneco Oil Company	8. Farm or Lease Name State LF-30
3. Address of Operator 7990 IH 10 West, San Antonio, Texas 78230	9. Well No. 2
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>1480</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>16S</u> RANGE <u>34E</u> N.M.P.M.	10. Field and Pool, or Wildcat Kemnitz Atoka Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 4143 GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☒

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER Perforated additional perfs ☒
and acidized.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. Make gauge ring run to 13,018.
- 2) Set retrievable plug in "F" nipple @ 13,018.
- 3) Load tubing, release packer, and circulate & condition hole.
- 4) POH w/tubing. Perforate Atoka @ 12,750-12,764' (56 shots) w/casing gun.
- 5) RIH w/packet set @ 12,600'. Swab well & test.
- 6) Acidize w/2500 gal 10% HCl. Swab & test.
- 7) RIH w/wireline & retrieve plug @ 13,018.
- 8) Commingle production Morrow & Atoka.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Project Production Engineer DATE 3/2/87

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE _____

DATE MAR 9 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 6 1967
SEC
HHS OFFICE

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANITARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Tenneco Oil Company		8. Farm or Lease Name State LF-30
3. Address of Operator 7990 IH 10 West, San Antonio, Texas 78230		9. Well No. 2
4. Location of Well UNIT LETTER <u>K</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>1480</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>16S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat S. Kemnitz Atoka Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 4143 GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Perforate additional pay & acidize</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. Make gauge ring run to 13,018.
- 2) Set retrievable plug in "F" nipple @ 13,018.
- 3) Load tubing, release packer, and circulate & condition hole.
- 4) POH w/tubing. Perforate Atoka @ 12,750-12,764' (56 shots) w/casing gun.
- 5) RIH w/packer set @ 12,600'. Swab well & test.
- 6) Acidize w/2500 gal 10% HCl. Swab & test.
- 7) RIH w/wireline & retrieve plug @ 13018.
- 8) Commingle production Morrow & Atoka.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Project Production Engineer DATE 1/13/87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JAN 22 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JAN 21 1985
FIDELITY OFFICE