

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Marathon Oil Company	8. Farm or Lease Name Delmont L. Hatfield
3. Address of Operator P. O. Box 2409, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> <u>1765</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>23</u> TOWNSHIP <u>16-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat wildcat
15. Elevation (Show whether DF, RT, GR, etc.) GR 3696 KB 3715	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>complete well</u> <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Marathon Oil Company proposes to:

Clean out well to PBTD + 8450'

Run CBL fr/ PBTD to 4100

Perforate the Abo Formation @ 8253-8417 W/1JSPF (47 holes)

Swab test and acidize, if necessary.

Cleaning out began 11-14-81

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ralph M. DePauw TITLE Production Engineer DATE 11-16-81

APPROVED BY Orig. Signed by TITLE  DATE NOV 22 1981

CONDITIONS OF APPROVAL (SEE PAGE 1)