

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT ..." (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER **Dry Hole**

Name of Operator
Bandera Energy Company

Address of Operator
505 N. Big Spring, Suite 400, Midland, Texas 79701

Location of Well
UNIT LETTER **H** **1980** FEET FROM THE **North** LINE AND **660** FEET FROM
THE **East** LINE, SECTION **27** TOWNSHIP **16-S** RANGE **35-E** NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
Eidson 27

9. Well No.
1

10. Field and Pool, or Wildcat
Wildcat

12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3973 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
NULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Drilled 7 7/8" hole to TD 13,066' on Jan. 1, 1982. Received plugging approval from Mr. J. T. Sexton.
2. Hole full of 10.2# mud. Set six 50 sx cmt plugs w/DP @ 11,950', 11,450', 10,450', 9600', 6300', 5000'. (9 5/8" csg set @ 5000' & cmtd to surface.)
3. Perforate & test Queen 4082-4106 & 4179-4180 and acidize w/2000 gals 15%. Swb dry, no show oil or gas
4. Ran tbg open ended to 4079', fill hole w/9.5# brine mix w/8 sx RW C-6. Spot 50 sx PU 10 stands. WOC 12 hrs. Lower tbg, found hard cmt @ 3956'. Pulled tbg to 1854' spot 36 sx cmt. Pull tbg out of hole. Cut off casing head. Set 10 sx plug into top 9 5/8" csg, weld on plate, install well marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY *Charles H. Huxley* TITLE Manager of Operations DATE 2-1-82

APPROVED BY *Ronald M. [Signature]* TITLE OIL & GAS INSPECTOR DATE JUN 24 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 24 1982
C. J. O.
HOBBY OFFICE