

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-27567

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Santa Fe Energy Operating Partners, L.P.

3. Address of Operator
550 W. Texas, Suite 1330, Midland, Texas 79701

4. Well Location
Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line
Section 11 Township 15S Range 32E NMPM 32E County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4297' DF

7. Lease Name or Unit Agreement Name

State NM "11"

8. Well No. 2

9. Pool name or Wildcat
Tulk (Wolfcamp)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Santa Fe Energy Oper. Part, LP intends to plug and abandon the subject well as follows:

1. Notify NMOCD at least 24 hours prior to beginning operations.
2. Circ hole w/ 9.5 ppg mud-laden fluid. Spot a 15 sx (135') Class "H" plug @ 11,500' to cover Atoka top.
3. Set a CIBP @ 9860' and spot Class "H" plugs as follows:

Depth to EOT	Sacks	Est. Height	Purpose
9860'	10	90'	On top of CIBP
8990'	15	135'	Cover Wolfcamp top

4. Run free-point on 5-1/2". Cut off and pull same. RIH w/ OE tubing and spot Class "C" plugs as follows:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McCullough TITLE Sr. Production Clerk DATE 6-28-94
TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 915/687-3551

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUL 01 1994

CONDITIONS OF APPROVAL, IF ANY:

State NM "11" No. 2
(Cont.)

4. <u>Depth to EOT</u>	<u>Sacks</u>	<u>Est. Height</u>	<u>Purpose</u>
50' inside 5-1/2"			
casing stub	35	133'	Cover stub
5490'	55	147'	Glorietta
4170'	40	125'	8-5/8" shoe
1483'	33	150'	Rustler
470'	33	150'	13-3/8" shoe
50'	13	50'	Surface

5. Cut-off wellhead 3' below ground level and install P&A marker.

Spud 10-11-81

State NM 11 No. 2

1980' FNL & 660' FWL
Sec 11-15S-32E, NMPM
Lea County, New Mexico
Ref: KB 4297 or 15' AGL

Formation Tops

13 3/8" 54.5# K-55 ST4C @ 420'
w/420 5x"C".

Rustler 1483'

Yates 2540'

San Andres 4035'

8 5/8" 32# S-80 @ 4120' w/
2750 5x (cmt circ to surf)

Glorietta 5489'

2 3/8" 4.7# N-80 tbg

2% KCL

ABO 7578'

TOC on 5 1/2" @ 7984' (CBL)

Wolfcamp 8970'

RTTS pkr @ 9810' (run 6-89)

Penn 10,120'

Strawn 11267'

Atoka 11503'

Morrow 11935'

11980'

9941'

9966'

9996'

CIB @ 12015' capped w/35' cmt

12336'

12344'

Mississippian 12374'

12374' w2

5 1/2" 17# 20# N-80 LT4C @ 12,440'
w/1300 9x H 50:50 Poz.

5 1/2" detail
0-9988' 17#
9988-TD 20#

TD 12,440'

1-13-94/AJW