

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR ARCO Oil and Gas Company
Division of Atlantic Richfield Company

3. ADDRESS OF OPERATOR
P. O. Box 1710, Hobbs, N M 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2630' FSL & 1310' FEL
AT TOP PROD. INTERVAL: as above
AT TOTAL DEPTH: as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input checked="" type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

LEASE LC-059152 (b)	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME Johns "B" DE	
9. WELL NO. 14	
10. FIELD OR WILDCAT NAME Maljamar Queen	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 24-17S-32E	
12. COUNTY OR PARISH Lea	13. STATE N M
14. API NO. 30-025-27654	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 4078.7' GR	

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged & Abandoned in the following manner:

RU on 12/22/83. POH w/rods & pump. Installed BOP & POH w/CA. Loaded 4½" csg w/ brine wtr. Set CR @ 3390'. Cmt'd perfs 3442-3460' w/100 sx Cl "H" Neat cmt, press to 2000#. RO cmt to 3328'. Displaced hole w/gelled 9.5# brine wtr. Perf'd 4½" csg @ 2050' w/4 holes. Pmp'd into holes, 4 BPM @ 1800#. POH w/pkr. Set CR @ 1939' & cmt'd thru perfs @ 2050' w/200 sx Cl "H" Neat cmt. Spot 5 sx cmt on top of ret. TOC @ 1875'. RO 4½" csg clean. Displaced 4½" csg w/9.5# brine gelled w/25# gel/bbl. RIH w/tbg OE to 500'. Displaced 4½" csg 500' to surf w/50 sx Cl "H" Neat cmt. Cut-off wellhead below GL & installed regulation dry hole marker. Welded cap over 4½" csg below surf. P&A eff: 12/28/83. Cleaned location for abandon-ment.

FINAL REPORT.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Colandrea Lawrence TITLE Drlg. Engr. DATE 12/28/83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 12/14/86
CONDITIONS OF APPROVAL, IF ANY: