

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texas Crude, Inc.	8. Farm or Lease Name Caudill "8"
3. Address of Operator P.O. Box 2359, Midland, TX 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>15-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3822' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

08-04-82:

Set plugs as follows: Plug #1 (35 sxs) 11,802-11,680'  
Plug #2 (35 sxs) 11,276-11,153'  
Plug #3 (35 sxs) 10,170-10,047'  
Plug #4 (35 sxs) 9,890-9,767'  
Plug #5 (35 sxs) 8,360-8,263'  
Plug #6 (35 sxs) 6,440-6,317'  
Plug #7 (35 sxs) 4,933-4,810'

08-05-82: Released rig @ 4:00 p.m.

10-01-82: Set surface plug @ surface w/10 sxs & weld plate and dry hole marker.

11-18-82: Cleaned pits, location & repair roads. Location ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jack D. Shonster TITLE Exploration Manager DATE 09/30/86

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE OCT 3 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
OCT 1 1986  
C. C. B.  
HARRIS OFFICE