Submit 3 Copies to Appropriate District Office

## State of New Mexico

Form C-103

Energy, Minerals and Natural Resources Department Revised 1-1-89 OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-625-27891 Santa Fe, New Mexico 87504-2088 DISTRICT P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE KY 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 None SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Tilley 758 1. Type of Well: OIL X GAS WELL 2. Name of Operator 8. Well No. Kennedy & Mitchell, Inc. 9. Pool name or Wildcat 500 N. Loraine Suite 1050 Midland, TX 79702 Shoebar Sevanias Well Location Unit Letter N : 330 Feet From The South \_\_ Line and \_\_\_\_\_1815 Feet From The \_\_\_ Lea 16S **NMPM** Township Range County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3965' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: X PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER:\_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Trip in hole w/ tbg to 12,450' +/-. Pump 25 sx cement. WOC 3-4 hours. Lower tbg and tag plug. Circulate hole with 10# salt gel mud. Pull tbg to 9,500' +/-. Pump 25 sx cement. Pull tbg to 6,500' +/-. Pump 25 sx cement. POH w/ tbg. Cut 5-1/2" csg at approx. 4,900' +/-. Lay down same. TIH w/ tbg to cut-off point. Spot 50 sx cement. WOC 3-4 hours. Tag plug w/ tbg. Pull tbg to 400' +/-. Pump 30 sx cement. POH w/ tbg and spot 10 sx cement at surface. Cut off wellhead and erect permanent marker. Current Wellbore Configuration: 13-3/8" 40# @ 378' (cemented to surface) THE COMMISSION MUST BE NOTHED 24 8-5/8" 24# & 32# @ 4,851' (cemented to surface) HO IN 100 182 BEGINNING OF Pres 1943 OPERATIONS FOR THE C-100 Open hole from 12,508' to 12,558' (TD) THE BE APPROVED. Projected date to commence Plug and Abandon is 1/13/92 I hereby certify that the information shove is true and complete to the best of my knowledge and belief. mue Production Supertendent 12-27-91 SKINATURE Jim McAninch ' (915) 684-7732 TELEPHONE NO TYPE OR PRINT NAME

CONDITIONS OF APPROVAL, IF ANY:

The ACTION BY JERRY SEXTON 115/1988V/50R

(This space for State Use)

APPROVED BY ...