

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
LG 880

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator
Yates Petroleum Corporation
Address of Operator
207 South 4th St., Artesia, NM 88210
Location of Well
UNIT LETTER B 660 FEET FROM THE North LINE AND 2310 FEET FROM
THE East LINE, SECTION 23 TOWNSHIP 15S RANGE 33E NMPA.
15. Elevation (Show whether DF, RT, GR, etc.)
4166' GR
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☒ Lost circulation plugs

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-9-83. Lost circulation 10740'. Set lost circulation plugs as follows:
Plug #1: Spotted 50 sx Thixolite, 1#/sx Permacheck and 1/2#/sx celloseal. Tailed in w/25 sx Class H 2% CaCl2. PD 10:30 AM 6-10-83. Plug set set 10730'. WOC 1 hr & 30 minutes.
Plug #2: Tagged cement 10730'. Spotted 25 sx Thixoment H, 1/2#/sx Permacheck, 1/4#/sx celloseal. Tailed in w/50 sx Class H, 1/2#/sx Permacheck, 1/4#/sx celloseal. PD 12:40 PM 6-10-83. Plug set 10740'. WOC 3 hrs.
Plug #3: Tagged cement 10660'. Spotted 25 sx Thixoment H, 1/2# sx Permacheck and 1/4#/sx celloseal. Tailed in w/50 sx Class H, 1/2#/sx Permacheck, 1/4#/sx celloseal. PD 5:03 PM 6-10-83. Plug set 10650'. WOC 6 hrs.
Plug #4: Tagged cement 10560'. Spotted 25 sx Thixoment H, 2#/sx Permacheck and 1/4#/sx celloseal. Tailed in w/50 sx Class H 2#/sx Permacheck and 1/4#/sack celloseal. PD 11:50 PM 6-10-83. Plug set 10554'. WOC 4 hrs.
Plug #5: Tagged cement 10660'. Spotted 25 sx Thixoment H, 2#/sx Permacheck and 1/4# sx celloseal. Tailed in w/50 sx Class H 2#/sx Permacheck and 1/4#/sx celloseal. PD 4:10 AM 6-11-83. Plug set 10554'. WOC 3-3/4 hrs. Tagged cement 10604'. Began drilling and lost circulation at 10740. Dry drilled to 10865'.
Plug #6: Spotted 100 sx Thixad H, 5#/sx Permacheck and 1/4#/sx celloseal. PD 11:00 AM 6-12-83. Plug set 10772'. WOC 4 hrs.

(continued)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Production Supervisor DATE 6-20-83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 24 1983
CONDITIONS OF APPROVAL, IF ANY: