

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ For ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Marathon Oil Company	8. Farm or Lease Name A. C. Taylor
3. Address of Operator P.O. Box 2409 Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>35</u> TOWNSHIP <u>16S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or WHdcat Undesignated
11. Elevation (Show whether DF, RT, GR, etc.) 4256 GR, 4270 KB	12. County Lea

10.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Completion Operations</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up Halliburton and acidized Queen perforations 3450 - 3470 and 3758 - 3768 with 4000 gallons of 15% NE acid. Using 500# rock salt and 25 ball sealers to divert with. Released Halliburton and began swabbing on the well. Released the packer and pulled out of the hole. Ran in the hole with 2 3/8" tubing and seating nipple. Landed the tubing at 3804'. Ran in the hole with rod pump and rods. Started well pumping to the frac tank to recover the load and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Steven A. Pohler TITLE Production Engineer DATE 3-18-83ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISORAPPROVED BY _____ TITLE _____ DATE MAR 22 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 21 1983

O.C.D.
HOBBS OFFICE