

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 958	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Laddie WC State
3. Address of Operator 105 South 4th St., Artesia, NM 88210		9. Well No. 2
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>11</u> TOWNSHIP <u>15S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or WHdcat Penn Saunders Permo Upper
15. Elevation (Show whether DF, RT, GR, etc.) 4180.5' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <u>Well status</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 7-30-86. RUPU. Attempted to unseat pump. Backed off rods. COOH w/249 rods.
 7-31-86. Continued working on freeing tubing anchor.
 8-1-86. Worked tubing until 11:00 AM. GIH w/rods to attempt to fish rods. Screwed into rods. COOH with remainder of rods. Left pump in hole.
 8-5-86. RIH w/2-1/2" paraffin knife w/2-1/5" washer to 7450'. Spudded thru tight spot and RIH to 10016'. POOH. RIH w/overshot, would not go past 30'. POOH. Ran 1-3/4" sinker bar. Stopped at 7450'. POOH.
 8-6-86. RIH w/2" and 1-3/4" OD gauge to 7835'. RIH w/1-5/8" gauge to 10016'.
 8-10-86. RDPU.
 8-28-86. RUPU. Pulled on tubing, and tubing would not move. Applied torque to tubing, would not move. Shut down.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Production Supervisor DATE 9-3-86

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT I SUPERVISOR TITLE DATE SEP 5 1986

CONDITIONS OF APPROVAL, IF ANY: