

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

30-025-28233

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Harvey E. Yates Company	8. Farm or Lease Name Vawter
3. Address of Operator P. O. Box 1933, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>31</u> TOWNSHIP <u>15S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat Townsend Permo Up. Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4018.5 GL	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/16/83 Plug & Abandon Well as follows:

1st plug: 34 sxs @ 11,440' - 11,340'.
2nd plug: 42 sxs @ 9,741' - 9,641'.
3rd plug: 51 sxs @ 8,383' - 8,283'.
4th plug: 42 sxs @ 6,143' - 6,043'.
5th plug: 40 sxs @ 4,650' - 4,550'.
6th plug: 30 sxs @ 1,800' - 1,700'.
7th plug: 10 sxs @ on surface.

Install dry hole marker @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE Reservoir Engineer

DATE July 20, 1983

APPROVED BY

TITLE OIL & GAS INSPECTOR

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 10 1983

77