Energy, Mineral.

Paur Hartis

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

Tate of New Mexico .d Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I	OIL C	ONSERVATIO	ON DIVIS	ION				
P.O. Box 1980, Hobbs, NM 88241-1980	2040 South Pacheco Santa Fe, New Mexico 87505				well api no. 30-025-28390			
DISTRICT II 811 S. First Street, Artesia, NM 88210					5. Indicate Type of Lease	STATE	X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410					6. State Oil & Gas Lease No. LG-1485			
SUND	RY NOTICES AND	REPORTS ON	WELLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)					7. Lease Name or Unit Agrees	ment Name		
I. Type of Well: OIL GAS WELL X WELL		OTHER			NEWMONT 16 S	TATE		
. Name of Operator					8. Well No.			
ELK OIL	. COMPANY				1			
3. Address of Operator	9. Pool Name or Wildcat							
POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-03					DENTON WOLFCAMP			
Unit Letter K	1980	Feet From The	SOUTH	Line and	1980 Fee	et From The	WEST	T_Line
Section 16	Township	15 SOUTH		Range 37 E.	AST NMPM	LEA	Coun	ıty
		10. Elevation (Show when 3832' RKB	ther DF, RKB, RT	, GR, etc.)				
11.			dicate Nati	ure of Notice. Re	port, or Other Data			
71 1					SUBSEQUENT REF	ORT OF:		
PERFORM REMEDIAL WORK	PLUG AN	D ABANDON	X	REMEDIAL WORK		ALTERING CASIN	1G	
TEMPORARILY ABANDON CHANGE PLANS				COMMENCE DRILLING OFNS. PLUG AND ABANDONMENT				
PULL OR ALTER CASING				CASING TEST AND CEMENT JOB				
OTHER.				OTHER:				
12. Describe Proposed or Completed (SEE RULE 1103	Operations (Clearly state all p	ertinent details, and give	e pertinent dates	, including estimated dat	e of starting any proposed wor	(16)		
INTEND	TO PLUG AND AB	ANDON WELL	AS FOLLO	WS: THE	COMMISSION MUS	CT DE NVST	HEIED 24	
1. SET CIB	S PRIOR TO THE BEGINNING OF							
2. CUT & R	GING OPERATIONS FOR THE C-103							
2. CUT & RECOVER 8800' ± OF 5 1/2" CASING. PLUGGING OPERATIONS FOR THE CHOR. TO BE APPROVED.								
	•	0017 @ 0000.			•			
4. SET 100' PLUG @ 6800'.								
5. SET 100' PLUG (50 IN / 50 OUT) @ 4952 (9 5/8 SHOE).								
6. SET 100' PLUG INSIDE 9 5/8 @ 2000'. TOP OF SALT. 7. SET 100' PLUG INSIDE 9 5/8 @ 575' (13 3/8 SHOE).								
	XS SURFACE PLU	- '	io onoc).					
0. 321 10 0	NO SOM ACE PE	og.						
Thereby certify that the information about	ve is true and complete to the b	est of my knowledge and b	belier.		·		···	
SIGNATURE		TITLE	PRESI	DENT		DATE	9/30/9	8
TYPE OR PRINT NAME	JOSEPH J. KELI	_Y			TELEPHONE	E NO.	505-623-31	190
(This space for State Use)	Acce Sie	ents on the						



DATE