NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		-1-03
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5. State Oil & Gas Lease No.
	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
I. OIL GAS WELL	other. Dry Hole	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
BTA OIL PRODUCERS		Casey, 8201 JV-P
3. Address of Operator 104 South Pecos	Midland, Texas 79701	9. Well No.
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER HH	1980 FEET FROM THE North LINE AND 660 FE	Casey-Strawn
THE East LINE, SECT	TION 27 TOWNSHIP 16-E RANGE 37-E	_ NMPM.
mannana da	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Ö	3778' GR	Lea
Check	Appropriate Box To Indicate Nature of Notice, Report	or Other Data
NOTICE OF	INTENTION TO: SUBSEC	QUENT REPORT OF:
	_	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	_	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK . COMMENCE DRILLING OPNS.	ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed (work) SEE RULE 1103.	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER OTHER Operations (Clearly state all pertinent details, and give pertinent dates, in	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103.	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER Operations (Clearly state all pertinent details, and give pertinent dates, in	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed of work) SEE RULE 1103. 4/6/84 Dry Ho #1	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER Operations (Clearly state all pertinent details, and give pertinent dates, in ole, Spotted P&A Plugs as Follows: 75 sx 6,984 - 6,784	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed (work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in Ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314'	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed of work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2 #3	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER OPErations (Clearly state all pertinent details, and give pertinent dates, in Ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314' 60 sx 4,489' - 4,289'	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed (work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2 #3 #4	PLUG AND ABANDON X CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314' 60 sx 4,489' - 4,289' 75 sx 2,232' - 2,032'	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed (work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2 #3 #4	PLUG AND ABANDON X REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER OPErations (Clearly state all pertinent details, and give pertinent dates, in Ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314' 60 sx 4,489' - 4,289'	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed of work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2 #3 #4 4/7/84 Spotte	PLUG AND ABANDON X CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314' 60 sx 4,489' - 4,289' 75 sx 2,232' - 2,032'	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed of work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2 #3 6 #4 4/7/84 Spotte #5 #6	PLUG AND ABANDON X CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in Ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314' 60 sx 4,489' - 4,289' 75 sx 2,232' - 2,032' ed Final P&A Plugs. 75 sx 612' - 412'	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed of work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2 #3 #4 4/7/84 Spotte #5 #6	PLUG AND ABANDON X CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314' 60 sx 4,489' - 4,289' 75 sx 2,232' - 2,032' ed Final P&A Plugs. 75 sx 612' - 412' 10 sx @ Surface Released Rig 2:00 PM	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed of work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2 #3 #4 4/7/84 Spotte #5 #6	PLUG AND ABANDON X CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OPErations (Clearly state all pertinent details, and give pertinent dates, in ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314' 60 sx 4,489' - 4,289' 75 sx 2,232' - 2,032' ed Final P&A Plugs. 75 sx 612' - 412' 10 sx @ Surface	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed of work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2 #3 #4 4/7/84 Spotte #5 #6	PLUG AND ABANDON X CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314' 60 sx 4,489' - 4,289' 75 sx 2,232' - 2,032' ed Final P&A Plugs. 75 sx 612' - 412' 10 sx @ Surface Released Rig 2:00 PM	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed of Completed (work) SEE RULE 1103. 4/6/84 Dry Ho #1 #2 #3 #4 4/7/84 Spotte #5 #6	PLUG AND ABANDON X CHANGE PLANS CHANGE PLANS CASING TEST AND CEMENT JQB OTHER OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in ole, Spotted P&A Plugs as Follows: 75 sx 6,984' - 6,784' 75 sx 5,514' - 4,314' 60 sx 4,489' - 4,289' 75 sx 2,232' - 2,032' ed Final P&A Plugs. 75 sx 612' - 412' 10 sx @ Surface Released Rig 2:00 PM	ALTERING CASING PLUG AND ABANDONMENT X

Installed Dry Hole Marker. Well P&A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED JOK. Newford BOB K. NEWLANDLE Regulatory Administrator

DATE 4/11/84

OIL & GAS INSPECTOR

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 1 6 1984

O.C.D.