

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28562
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. NM 1364

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐ Converting to SWD	7. Lease Name or Unit Agreement Name KATHY FOLK
2. Name of Operator V-F PETROLEUM INC.	
3. Address of Operator ONE MARIENFELD PLACE, STE 580 MIDLAND, TX 79701	
4. Well Location Unit Letter <u>H</u> : <u>1800</u> Feet From The <u>NORTH</u> Line and <u>330</u> Feet From The <u>EAST</u> Line Section <u>32</u> Township <u>16S</u> Range <u>35E</u> NMPM LEA County	8. Well No. 1
9. Pool name or Wildcat VACUUM WOLFCAMP, NE	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4001' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: PLUG BACK FOR SWD CONVERSION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU WSU. INSTALL BOP.
2. RU WIRELINE TRUCK. SET CIBP ON WIRELINE @ 10,190'.
3. TIH W/ TBG. TAG CIBP @ 10,190'.
4. LOAD HOLE W/ MUD. SPOT 5 SX CMT PLUG FROM 10,190' - 10,090'. TOH.
5. NIPPLE DOWN BOP. & WH. SHOOT OFF 5 1/2" CSG @ 6250'. TOH W/ CSG.
6. INSTALL WH & BOP. TIH W/ TBG TO 6700'. LOAD HOLE W/ BRINE & FRESH WTR. SPOT 25 SX CMT PLUG FROM 6700' - 6500'. PULL TBG TO 6300'. SD. WOC.
7. TIH W/ TBG. TAG PLUG @ 6437'.
8. PERFORATE GLORIETA FROM 6331' - 35' w/ 16 HOLES. LOWER TBG TO 6360'. CIRC HOLE CLEAN.
9. SPOT 2000 GAL 15% NeFe HCL ACID OVER PERFS & SAN ANDRES OH INTERVAL.
10. PULL TBG TO 5100'. ACIDIZE W/ 3000GAL 15% NeFe HCL ACID. LOWER TBG TO 5450' & CONTINUE ACID JOB. ISDP - 2000#, 5" - 1300#.
11. NIPPLE DOWN BOP. SWI. WO PLASTIC-LINED PIPE & PACKER TO COMMENCE INJECTION OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kenneth E. Stull TITLE ENGINEERING TECHNICIAN DATE 3/2/93
TYPE OR PRINT NAME KENNETH E. STULL TELEPHONE NO. 683-3344

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY JERRY SEXTON SUPERVISOR TITLE _____ DATE MAR 04 1993
CONDITIONS OF APPROVAL, IF ANY:

3/10/93 3/14/93 (see back)