

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-28568

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Eidson #56-959

8. Well No.

1

9. Pool name or Wildcat

North Shoe Bar (Devonian)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Great Western Onshore Inc.

3. Address of Operator
1111 Bagby, Suite 1700, Houston, Texas 77002-2595

4. Well Location
Unit Letter C : 990 Feet From The North Line and 2310 Feet From The West Line
Section 15 Township 16S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3994' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐ Well P&A 3/14/93
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work from 3/3/93 to 3/14/93:

- 1) Plug #1 - 60 sx cement from 12,600'-11,743'.
- 2) Plug #2 - 25 sx from 9,000'-8,780'.
- 3) Plug #3 - 25 sx from 6,000'-5,780'.
- 4) Perf'd @ 4,750' w/4 shot perf strip. RIH w/tubing to 4,750'. Circ salt gel from 4,750' to surface.
- 5) Plug #4 - 85 sx cement from 4,750'-3,950'.
- 6) Perf'd @ 1,700' w/4 shot perf strip. RIH w/tubing to 1,700'. Circ 5-1/2" & 8-5/8" w/salt gel.
- 7) Plug #5 - 85 sx cement from 1,700'-900'.
- 8) Cut off wellhead.
- 9) Plug #6 - 10 sx cement 200' to surface.
- 10) Installed P&A marker and cleaned location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kathy Carten TITLE Supervisor, E&P Support DATE 4/5/93
TYPE OR PRINT NAME Kathy Carten TELEPHONE NO. 713/739-84

(This space for State Use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL IF ANY:

OIL & GAS INSPECTOR

DATE JAN 25 1994

RECEIVED

APR 08 1993

ODD HOBBS OFFICE