State of New Mexico Energy, insurerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobba, NM 88240 OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 2088	30-025-28611
P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DISTRICT III	STATE K FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	VA-821
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: OR. GAS WELL X WELL OTHER	Medusa ASG State
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No.
3. Address of Operator	1
105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat
4. Well Location	Wildcat Abo
Unit Letter L : 1980 Feet From The South Line and 660	Feet From The West Line
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM Lea County
//////////////////////////////////////	
11. Check Appropriate Box to Indicate Nature of Notice, R	eport, or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	GOPNS. PLUG AND ABANDONMENT X
PULL OR ALTER CASING CASING TEST AND CE	EMENT JOB
OTHER: OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, inclu-	ding estimated date of starting any proposed
work) SEE RULE 1103.	
2-27-98 - Moved in pulling unit. Shut down due to high wi	ind.
2-28-3-2-98 - Rigged up pulling unit. Nippled down wellhe	ead. Nippled up BOP. TIH
with tubing and tagged up. Unset packer. POOH with tubin	ig and packer. Rigged up wire-
line. RIH with CIBP and set at 9060'. Rigged down wireli Shut well in for night.	ne. RIH with tubing to 9060'.
3-3-98 - Circulated hole with mud laden fluid. Spotted 25	canaka Class C coment from
9060-8814'. POOH with tubing. Nippled down BOP and wellh	read Welded on pull cub
Shut down for night.	reduce on pull sub.
3-4-98 - Rigged up wireline. TIH with wireline (split sho	ot) and cut 5-1/2" casing at
7568'. POOH with wireline. Worked casing - casing not fr	ee. RIH with wireline and cut
casing at 7527'. POOH with wireline. Worked casing - cas	ing not free. RIH with wire-
line and cut casing at 7486'. POOH with wireline. Worked	
DIH said sais 11	casing - casing not free.
RIH with wireline and cut casing at 7406'. POOH with wire	line. Worked casing free.
RIH with wireline and cut casing at 7406'. POOH with wire POOH with 19 joints of 5-1/2" casing. NOTE: Casing was m	line. Worked casing free. ade up too tight. Collars
RIH with wireline and cut casing at 7406'. POOH with wire POOH with 19 joints of 5-1/2" casing. NOTE: Casing was m I hereby certify that the information above is true and complete to the best of my knowledge and belief.	line. Worked casing free. ade up too tight. Collars NTINUED ON NEXT PAGE:
RIH with wireline and cut casing at 7406'. POOH with wire POOH with 19 joints of 5-1/2" casing. NOTE: Casing was m I hereby certify that the information above is true and complete to the best of my knowledge and belief.	line. Worked casing free. ade up too tight. Collars
RIH with wireline and cut casing at 7406'. POOH with wire POOH with 19 joints of 5-1/2" casing. NOTE: Casing was m I hereby certify that the information above is true and complete to the best of my knowledge and belief.	line. Worked casing free. ade up too tight. Collars NTINUED ON NEXT PAGE:
RIH with wireline and cut casing at 7406'. POOH with wire POOH with 19 joints of 5-1/2" casing. NOTE: Casing was make the control of the cont	line. Worked casing free. ade up too tight. Collars NTINUED ON NEXT PAGE: echnician DATE March 16, 1998
RIH with wireline and cut casing at 7406'. POOH with wire POOH with 19 joints of 5-1/2" casing. NOTE: Casing was make the complete to the best of my knowledge and belief. SHONATURE RUST Klaip	line. Worked casing free. lade up too tight. Collars NTINUED ON NEXT PAGE: echnician DATE March 16, 1998 TELEPHONE NO. 505/748-14
RIH with wireline and cut casing at 7406'. POOH with wire POOH with 19 joints of 5-1/2" casing. NOTE: Casing was make the complete to the best of my knowledge and belief. SIGNATURE Rusty Klein Rusty Klein	line. Worked casing free. ade up too tight. Collars NTINUED ON NEXT PAGE: echnician DATE March 16, 1998