

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-28707
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Dry Hole		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator David H. Arrington Oil & Gas, Inc		6. State Oil & Gas Lease No. 27467
3. Address of Operator P.O. Box 2071, Midland, Texas 79702		7. Lease Name or Unit Agreement Name: Mallon Drake 16 State
4. Well Location Unit Letter <u>G</u> : <u>1330'</u> feet from the <u>North</u> line and <u>1650'</u> feet from the <u>East</u> line Section <u>16</u> Township <u>16S</u> Range <u>37E</u> NMPM County <u>Lea</u>		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3809' GR		9. Pool name or Wildcat Dean-Wolfcamp SE

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/19/01-Set 55 sxs plug from 12,164'-12,026' & LD 20 jts DP, set 35 sxs plug from 11,535'-11,435' & LD 26 jts DP, set 50 sxs plug from 10,660'-10,560' & LD 62 jts DP, set 45 sxs plug from 8600'-8500' & LD 24 jts DP, set 45 sxs plug from 7860'-7760' & LD 42 jts DP, set 55 sxs plug from 6563'-6463'.
5/20/01-LD 69 jts DP, POOH for plugged DP, LD 21 jts DP, TIH, set 55 sxs plug from 4400'-4300', POOH 10 stands, WOC, tagged cmt @ 4296', LD 69 jts DP, set 35 sxs plug from 2050'-2150' & LD 69 jts DP, set 10 sxs surface plug, RD LD machine, ND BOP's, clean steal pits & released rig @ 6:00 a.m.

Next time must set plug across surface shoe in order to protect Ogallala fresh water zone.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Chuck Sledge TITLE Engineer DATE 5/25/01

Type or print name Chuck Sledge Telephone No. (915) 682-6685
(This space for State use)

APPROVED BY Mary W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 24 2003
Conditions of approval, if any: WINK

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.