

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISIO.
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG 2552

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator SAGE ENERGY COMPANY	8. Farm or Lease Name Lowe State
3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702	9. Well No. 2
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 10 TOWNSHIP 15S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Sainders Permian Penn (Upper Penn)
15. Elevation (Show whether DF, RT, GR, etc.) 4188.5 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) CIBP + 20' at 9500' (Top of cement behind 5½" csg at 8600', cement circ. to surface on 8 5/8" csg.)
- 2.) Cut csg at ± 6000'. spot 30 sx at 5950' - 6050'
- 3.) Spot 30 sx 4180' to 4280'
- 4.) Spot 30 sx. 360' to 460'
- 5.) 10 sx. at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Francis Halygas TITLE Production Clerk DATE 11-28-88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE DEC 2 1988

CONDITIONS OF APPROVAL, IF ANY: