

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Hamon Oil Company	8. Farm or Lease Name McDaniel
3. Address of Operator 611 Petroleum Building, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER K, 1980 FEET FROM THE south LINE AND 1980 FEET FROM THE west LINE, SECTION 14 TOWNSHIP 16-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3895' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set permanent CIBP at 11,762'.
- Circulated hole with 10# salt gel mud. Spotted a 75 sack Class H cement plug from 11,762' back to 11,104'.
- Set 35 sx Class H cement plug from 9650' to 9450'. WOC and tagged plug at 9408'.
- Cut and pulled 5-1/2" casing at 8020'.
- Set 50 sx cement plug from 8048' to 7970'. WOC, tagged at 7888'.
- Set 50 sx cement plug from 6358' to 6258'. WOC, tagged at 6240'.
- Set 75 sx cement plug from 4946' to 4846'. WOC, tagged at 4770'.
- Set 50 sx cement plug from 2200' to 2100'. WOC, tagged at 2085'.
- Set 50 sx cement plug from 467' to 367'. WOC, tagged at 328'.
- Set 10 sx cement plug in top of 8-5/8" casing.
- Installed dry hole marker. P&A 3:00 P.M. 12-11-84.
- Commission will be notified when final clean up is made.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Engineer DATE 12/12/84

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE 4-1-85

CONDITIONS OF APPROVAL, IF ANY: