

November 19, 1984

Summary of Drill Stem Test:

Ran Drill Stem Test on Zip Franklin #1 on 10-27-84. Test showed well blow throughout and recovered 985 feet of fluid being 90 feet of drilling fluid on top and 895 feet of formation water, slightly cut with drilling fluid. Test showed no oil or gas whatsoever.